

## Department of Environmental Conservation

DIVISION OF SPILL PREVENTION AND RESPONSE Contaminated Sites Program

410 Willoughby Ave., Suite 303 P.O. Box 111800 Juneau, Alaska 99811-1800 Main: 907.465.5390 Fax: 907.465.5218 www.dec.alaska.gov

File: 1513.38.074

Certified Mail, Return Receipt Requested Article No. 7014 2120 0001 4210 0827

July 19, 2016

City & Borough of Juneau Attn: Rorie Watt, City Manager 155 South Seward Street Juneau, AK 99801

Re: Oil-water separator maintenance at Holy Trinity Episcopal Church, located at 325 Gold Street in Juneau, Alaska 99801

This letter is being issued as a reminder of the conditions placed on the Holy Trinity Episcopal Church property as part of the 2014 Cleanup Complete Determination Amended Decision granted by the Alaska Department of Environmental Conservation (ADEC), and the subsequent Maintenance of the oil-water separator agreement that was signed by the City & Borough of Juneau (CBJ) City Manager at that time, Kimberly A. Kiefer.

The oil-water separator installed onsite requires yearly inspections and cleanings for the removal of accumulated sediments, oils, and other pollutants. The CBJ has agreed to maintain, pump, and clean the oil-water separator every year in the month of June. Record of the maintenance activities performed on the oil-water separator are to be held onsite by the Holy Trinity Episcopal Church and be available upon written or verbal request.

Please be aware that the Holy Trinity Episcopal Church site is also subject to the following site-specific conditions and/or controls, as established in the 2014 Amended Determination:

- 1. Pursuant to 18 AAC 75.325(i)(1) and (2), ADEC approval is required prior to moving soil or groundwater that is, or has been, subject to the cleanup rules found at 18 AAC 75.325-.370. In the future, if soil is removed from the site it must be characterized and managed following regulations applicable at that time. A "site" [as defined by 18 AAC 75.990 (115)] means an area that is contaminated, including areas contaminated by the migration of hazardous substances from a source area, regardless of property ownership.
- 2. Movement or use of contaminated material in a manner that results in a violation of 18 AAC 70 water quality standards is prohibited.

3. Subsurface soil contaminated is presumed present at a depth of between 8-12 feet on the northeast corner of the property. Figure 1 (in the original 2012 Decision Document) shows the location of the area where petroleum contamination was found migrating onto the property.

This site information is a matter of public record and is available at ADEC's online database record at: <a href="http://dec.alaska.gov/Applications/SPAR/PublicMVC/CSP/SiteReport/4455">http://dec.alaska.gov/Applications/SPAR/PublicMVC/CSP/SiteReport/4455</a>

The ADEC will contact CBJ on an annual basis to verify that the oil-water separator maintenance has been performed. The Holy Trinity Episcopal Church will be contacted every five years to verify land use conditions remain unchanged.

If you have any questions regarding this site, please contact me at (907) 465-5229 or evonne.reese@alaska.gov and I will be glad to assist you.

Sincerely,

Evonne Reese

Environmental Program Specialist

Institutional Control Unit

Encl: 2014 Maintenance of the oil-water separator agreement

2014 Cleanup Complete Determination Amended Decision

CC: Father Gordon Blue – Holy Trinity Episcopal Church

John Pollard, Senior Warden - Holy Trinity Episcopal Church