

PHOTOGRAPHS



Photograph 1. Mill site and associated waste rock and tailings.



Photograph 2. Electric locomotive.



Photograph 3. One of several drum caches.



Photograph 4. Former location of building C4.



Photograph 5. AST area near mill site.



Photograph 6. Unsaturated tailings beneath mill.



Photograph 7. Test holes advanced near barge, November 2009.



Photograph 8. Location of waste rock sample collected from D1 and rock mixed in with mine tailings.



Photograph 9. Location of mill site repository between Unnamed Stream and mill site.



Photograph 10. Borrow Pit West (Alternative 2 Primary) repository.



Photograph 11. Borrow Pit East (Alternative 2 Secondary) repository.