

Subarea	GRS Site Name	Site No.	Errata	Date
PWS	Anderson Bay	NE-22	<b>NE 22-02, Implementation</b>	21Nov16
			Added: "Tidal-seal boom not appropriate for use at either the eastern or western shore anchor locations."	
			<b>NE-22-02, Special Considerations</b>	21Nov16
			Changed date for "Tested" to September 10, 2016	
			<b>NE-22-03, Location and Description</b>	21Nov16
			Added: "Eastern and Western shorelines not suitable for shore seal boom."	
			Added: "Submerged rocks pose significant navigation hazards at the western shore anchor."	
			<b>NE-22-03, Implementation</b>	21Nov16
			Removed: "Tidal seal boom not appropriate for use at either the eastern or western shore anchor locations."	
			Removed: "Submerged rocks pose significant navigation hazards at the western shore anchor."	
			<b>NE-22-03, Special Considerations</b>	21Nov16
			Changed date for "Tested" to September 10, 2016	
			<b>Layout Changes</b>	21Nov16
			Updated main map to 2016 GIS NOAA Raster Nav. Chart, Removed tidal seal boom icons from eastern and western boom shore anchor locations, added Location map with callout, removed two photos.	