Sound Ocean
Metal Fabricators Ltd.

PROCESS STEPS FOR BERING SELECT COD LIVER OIL PLANT

1. Receiving
2. Thawing
3. Grinding
4. Contherm (cooking)
5. Decanters (separating)
6. Centrifuge
7. Tote Filling/Labeling
8. Shipping