

Bonanza Hill
Dexter Peak
Dexter
Banner Peak
Banner
Summit
Anvil Mountain
North Peak
Newton Peak
Perkinsville
2 a & b
1 a & b
3
4
5


Banner
Peak
Secondary Recharge Area
Pzg
Primary Recharge Area
Pzg
SS-3
SS-2
gt
Pzm
Moonlight Springs