WB File
43(b)

Luke Hood Sampling

Hammer Slough

Erosion - city yard, -

No water quality monitoring done

Right Fork - pink + coho

Left Fork - been laid too steep to resolve problem

Installed Culvert - Culvert has too steep of gradient to allow for fish

Haven't

Tremendous amount of siltation

Runoff from Lower city streets

Major source of urban Runoff

Lower Hammer slew - they have dredged out boat harbor -

Lower Hammer slow - sediment from streets

Most of sediment is Human Induced
Hammer Slough :