555 Cordova Street
Anchorage, AK 99501
PHONE: (907) 269-7552
FAX: (907) 269-7649
http://www.state.ak.us/dec/home.htm

DIVISION OF SPILL PREVENTION AND RESPONSE
CONTAMINATED SITES PROGRAM

File No.: 2101.38.049
Database Reckey No.: 199721X119801

July 23, 2004

3 CES/CC
Attn: John Mahaffey
6326 Arctic Warrior Drive
Elmendorf AFB, AK 99506-3240

RE: SS704/8 Hardstand #39 SS704, EC Contaminated Site Decision Documents, Elmendorf Air Force Base, AK Dated April 23, 2004

Dear Mr. Mahaffey:

On April 26, 2004, the Alaska Department of Environmental Conservation (the Department) received several decision document packets. After reviewing the data and reports submitted for SS704/8, the Department agrees that no additional remediation or investigation is required for SS704/8 Database RecKey no. 199721X119801. However, groundwater monitoring will be required until cleanup levels are achieved.

The Department reserves its rights, under: 18 AAC 75 Contaminated Site regulations and AS 46.03 to require additional investigation, cleanup, containment, and/or other necessary actions, if subsequent information indicates: additional contamination remains at the site which was previously undiscovered and presents an unacceptable risk to human health, safety, or welfare, or the environment.

If you have any questions regarding this letter, please call me at (907) 269-7552.

Sincerely,

Louis Howard
Project Manager
Federal Facilities Section