STATE OF ALASKA

FRANK H. MURKOWSKI, GOVERNOR

DEPT. OF ENVIRONMENTAL CONSERVATION

DIVISION OF SPILL PREVENTION AND RESPONSE
CONTAMINATED SITES PROGRAM

555 Cordova Street
Anchorage, AK 99501-2617
Phone: (907) 269–7552
Fax: (907) 269–7649
http://www.dec.state.ak.us

Database No.: 199421X124904
File No.: 2101.38.~~78~~ .078

September 22, 2005

3 CES/CEVR
Attn: Ellen Godden
6326 Arctic Warrior Drive
Elmendorf AFB, AK 99506-3240

RE: Draft Remedial Report PL81-Valve Pit 11 Soil Cleanup Elmendorf AFB, Alaska September 2005

Dear Ms. Godden:

The Alaska Department of Environmental Conservation (ADEC) received the document listed above on September 19, 2005. Based on the data and information provided, ADEC agrees with the Air Force's request that vadose zone soil remedial actions are complete and that no further action is necessary for vadose zone soil at this site.

ADEC reserves all of its rights, under A.S. 46.03, 18 AAC 75, and 18 AAC 78 to require the Air Force to conduct additional site assessment, monitoring, remediation, and/or other necessary actions at PL81-Valve Pit 11, if information becomes available that contamination is found at this site, which poses a threat to human health or safety, welfare, or the environment.

If you have any questions regarding this letter, please call me at (907) 269-7552.

Sincerely,

Louis Howard
Project Manager
Federal Facilities Section

G:\SPAR\SPAR-CS\38 Case Files (Contaminated Sites)\2101 Elmendorf AFB\2101.38.078 PL81 Base Fuel System North Jet Inactive Pipeline SERA\22-Sept-2005 PL81 Valve Pit 11 remedial report Concurrence.doc

Printed on Recycled Paper