STATE OF ALASKA

TONY KNOWLES, GOVERNOR

DEPT. OF ENVIRONMENTAL CONSERVATION

Contaminated Sites Remediation Program
Post Office Box 1542
Haines, Alaska 99827

phone: (907) 766-3184
fax: (907) 766-3184

September 26, 1997

Ms. Tracy Ricker
Ricker & Associates
400 Willoughby Ave.
Juneau, AK. 99801

RE: Goldbelt Place Building, 801 10th Street, Juneau

Dear Ms. Ricker:

The department has reviewed the Corrective Action Report which was submitted by your consultant, Easton Environmental, and concurs with the conclusion that all contaminated soil was excavated and removed. Thus, the department requests no further action for the Goldbelt Place Building at 801 10th Street in Juneau as all of the soil samples collected after the excavation of the tank and associated soils contained levels of petroleum constituents below the cleanup level. This site is now considered to be "closed" by the department and will be indicated as such on the department's Contaminated Sites Database.

Thank you for participating in the pilot of the Voluntary Cleanup Program. We are interested in how the VCP worked for you and would appreciate any suggestions for modification which you may have. We anticipate finalizing a new expanded version of the VCP in the winter which will retain the simple streamlined nature of the pilot while being consistent with the new Chapter 75 regulations. The draft VCP will be put out for public review and we will notify you when that occurs. If you have any questions about this letter or suggestions about how to improve the VCP, please do not hesitate to contact me. I can be reached by telephone and fax at 766-3184, by email at apalmier@envircon.state.ak.us, or by regular mail at P.O. Box 1542, Haines, AK. 99827.

Sincerely,

Anne Marie Palmieri

Anne Marie Palmieri
Environmental Specialist

cc: Easton Environmental (via facsimile)

a:\vcp\siteinfo\goldbeltnfa.doc