ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Spill Prevention and Response Prevention and Emergency Response Program

SITUATION REPORT As of 10:00 AM on May 7, 2010

INCIDENT NAME: Princess Kathleen **SITREP #**: 19

SPILL NUMBER: 10119904701 **LEDGER CODE**: 14284160

TIME/DATE OF SPILL: The S/S Princess Kathleen grounded and sank off Point Lena on September 7, 1952.

TIME/DATE OF SITUATION REPORT: 2:00 PM on May 7, 2010

TIME/DATE OF THE NEXT REPORT: 2:00 PM on May 10, 2010

TYPE/AMOUNT OF PRODUCT SPILLED: The total volume of number 6 bunker oil onboard the vessel at the time of sinking is unknown. The volume of bunker oil identified in 10 of the ship's tanks is estimated to be between 14,000 and 34,000 gallons. Four additional tanks remain to be surveyed. The volume of other oils that remain on the ship is currently unknown.

LOCATION: Point Lena, Favorite Channel, north of Juneau, Alaska.

<u>CAUSE OF SPILL</u>: The vessel grounded on Point Lena and suffered damage to the forward-most section of the bow. As the tide came in, the vessel flooded from the stern and slid off the point. The vessel now sits at an angle on its port side at a depth ranging from 52 feet at the bow to 134 feet at the stern. Recent increases in the frequency of sheen being reported in the area were investigated and traced to the *Princess Kathleen*, possibly indicating a change in the vessel's condition.

POTENTIAL RESPONSIBLE PARTY (PRP): Undetermined

RESPONSE ACTION: In response to elevated hydrogen sulfide levels last weekend, the compound Petro Sweet was delivered to the operations platform on May 4, 2010. Petro Sweet is a chemical compound used to neutralize hydrogen sulfide. Chemical technicians installed an injection system to mix the compound in the line that recovers fuel before it reaches the collection tank. The compound was also added to recovered fuel already in the collection tank and the tank barge. Crews continue a strict air monitoring program on site to ensure the safety of work crews.

Once Petro Sweet treatment commenced, Global Diving and Salvage (Global) resumed normal fuel pumping operations on the number 3 starboard wing tank. They completed fuel removal operations in the number 3 tank, collecting over 2,600 gallons of oil.

Global has successfully removed recoverable oil from three of the 14 fuel tanks on board the vessel. The total volume of oil recovered to date is approximately 22,270 gallons.

Global cleared asphalt and silt to gain access to the number 1 and 2 port wing tanks and have found the manhole covers on the top of the tanks. Work continues to clear silt and asphalt from the number 3 and 4 port wing tanks. Landing plates have been installed on the number 1 port wing tank.

Active booming operations are ongoing to contain the sheen produced by the *Princess Kathleen*. Boom is being adjusted as needed to ensure maximum containment and recovery of any sheen created.

SOURCE CONTROL: Global has installed temporary patches over the exposed starboard portholes to prevent oil trapped within the vessel from escaping. Global has plugged fuel tank vent pipes to prevent the loss of bunker oil

Sitrep 19

during fuel removal operations. Global crews identified and patched several rivets that were leaking oil. Crews have removed more than 22,000 gallons of fuel from the vessel to date.

RESOURCES AFFECTED: Shoreline Cleanup Assessment Technique (SCAT) team are conducting surveys to monitor impacts to sensitive areas. A few small quarter-size patches of oil have been found on shorelines near the fuel pumping operations. The oil is tar-like and very weathered, which suggest that it has been on the shore for a number of months or longer. SCAT team will be monitoring the shoreline to determine if any additional impacts are occurring during the fuel removal and cleanup operations.

SEAPRO has begun conducting active bird hazing in the area as a preventative measure. The Unified Command and NOAA have developed a communication plan for when marine mammals are observed in the vicinity. The *Princess Kathleen* is of historic significance and is listed as a historic shipwreck by the State of Alaska Office of History and Archeology.

<u>FUTURE PLANS AND RECOMMENDATIONS</u>: Work to provide access to the port wing tanks will continue. Fuel pumping operations will continue, moving from one fuel tank to the next.

WEATHER: Today: South winds increasing to 15 knots in the afternoon. Seas building to 3 feet. Tomorrow: South winds 15 knots, seas 3 feet.

UNIFIED COMMAND AND PERSONNEL:

F.O.S.C. : Capt. Melissa Bert, USCG S.O.S.C. : Scot W. Tiernan, ADEC

FOR ADDITIONAL INFORMATION CONTACT: Sarah Moore, ADEC, (907) 465-5239 or JIC officers at 463-2065.

Photographs and other spill information are available for viewing on the Unified Command website: www.dec.state.ak.us/spar/princesskathleen

AGENCY/STAKEHOLDER NOTIFICATION LIST

This sitrep has been distributed to the following agencies and stakeholders. The situation report was also distributed to the various agency staff listed on the standard distribution list. The receiving agencies listed in the standard distribution list includes: Governor's office, Senator Begich's office, ADF&G, ADNR, SECC, EPA, DOI, NMFS, USFWS, and USFS.

Agency/ Stakeholders	Name	Sent Via	Additional Info	Telephone	Fax
Senate Dist. B	Senator Dennis Egan	Fax	session	465-4947	465-2108
House Dist. 3	Representative Beth Kerttula	Fax	session	465-4766	465-4748
House Dist. 4	Representative Cathy Munoz	Fax	session	465-3744	465-2273
USCG (Sector Juneau)	Capt. Melissa Bert	Email	Melissa.bert@uscg.mil	463-2836	
USCG (Sector Juneau)	Lt. Latarsha McQueen	Email	Latarsha.s.mcqueen@uscg.mil	463-2835	463-2445
USCG (Sector Juneau)	Cdr. Matt Jones	Email	Matt.n.jones@uscg.mil	463-2452	
USCG (Sector Juneau)	Cdr. Kurt Clarke	Email	Kurt.a.clarke@uscg.mil	463-2475	
USCG (Sector Juneau)	MSTC James Highfill	Email	James.L.Highfill@uscg.mil	463-2461	
USDA Forest Service - Juneau Ranger District	District Ranger Pete Griffin	Email	pgriffin@fs.fed.us	789-6244	586-8808
USDA Forest Service - Tongass Env. Engineer	Michele Marie Parker	Email	mmparker@fs.fed.us	772-5850	772-5896
USDA Forest Service -	District RangerMarti	Email	mmmarshall01@fs.fed.us	789-6202	

Agency/ Stakeholders	Name	Sent Via	Additional Info	Telephone	Fax
Admiralty Island National	Marshall				
Monument					
NMFS	Jon Kurland	Email	Jon.kurland@noaa.gov	586-7638	586-7358
ADNR	Doug Sanvik	Email	Doug.Sanvik@alaska.gov		
ADF&G	Joe Hitselberger	Email	Joe.Hitselberger@alaska.gov	465-4346	465-4759
Douglas Indian	Doug Dobyns,	Email	DougDobyns@yahoo.com	364-2916	364-2917
Association	Environmental				
	Planner				
Central Council Tlingit and	L. Knight	E-mail	LKnight@ccthita.org		
Haida Indian Tribes of					
Alaska					
City and Borough of	Mayor Bruce Botelho	E-mail	city_clerk@ci.juneau.ak.us	586-5240	586-5385
Juneau					
SEAPRO	Dave Owings	Email	Dave@seapro.org		
SEAPRO	Cheryl Fultz	Email	Cheryl@seapro.org		



A drum of Petro Sweet within a secondary containment 'over pack' is transferred to a vessel via crane for delivery to the fuel recovery platform. May 4, 2010.