

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Spill Prevention and Response Prevention and Emergency Response Program

SITUATION REPORT

## Alaska Petroleum Mile 48 Richardson Hwy

SITREP #: 2

**SPILL #:** 14229934301



TIME/DATE OF DISTRIBUTION: 3:00 p.m. December 22, 2014

POTENTIAL RESPONSIBLE PARTY (PRP): Alaska Petroleum Distributors, Inc.

INCIDENT LOCATION: Mile 48 Richardson Highway

**TIME/DATE OF SPILL:** The vehicle accident occurred approximately 6:30 p.m. on December 9. Alaska Petroleum Distributors reported the incident to ADEC at 2:30 a.m. on December 10.

**HOW/WHEN SPILL WAS DISCOVERED:** Motor vehicle accident. Diesel fuel was released when the tank trailer overturned during winter driving conditions.

**TYPE/AMOUNT OF PRODUCT SPILLED:** Alaska Petroleum Distributors estimated approximately 4,400 gallons of low sulfur diesel fuel were released.

**CAUSE OF SPILL:** Winter driving conditions caused the vehicle to veer far to the right, causing the second tanker trailer to rollover into the ditch.

SOURCE CONTROL: None. All the fuel content in the tanker trailer was released to the environment.

**RESPONSE ACTION:** A response team consisting of Alaska Petroleum Distributors and their contractors, as well as ADEC, Environmental Protection Agency (EPA), Bureau of Land Management, and Alaska Department of Transportation Highway Safety Office, responded to the incident and began emergency response actions on Thursday December 11. Approximately 528 tons of contaminated material has either been removed to Fairbanks for treatment or stockpiled on site. Five groundwater monitoring wells have been installed and groundwater samples have been collected for lab analysis.

A disposal plan has been approved, which consists of all collected liquids and contaminated soils and other debris being transported to Anchorage and Fairbanks for disposal or treatment.

**RESOURCES AFFECTED:** The impacted area is currently estimated at 75 feet by 75 feet in the road right-of-way. The area contains numerous seasonal creeks and wetlands. Currently, the area is dry with no moving surface water. No wildlife has been observed in the area and there have been no reports of impacts to wildlife.

**FUTURE PLANS AND RECOMMENDATIONS:** The EPA has issued an Administrative Order requiring Alaska Petroleum Distributors to continue recovery efforts on the site. If Alaska Petroleum Distributors are unable to comply with the administrative order, the EPA will assume overall operational command of the project on December 23. The EPA will continue the Unified Command process and work with all agencies and stakeholders to continue the cleanup efforts. An EPA term contractor has been identified and the contract process has begun. On site responders will continue to maintain site security until the contract is in place, possibly by December 29<sup>th</sup>.

**WEATHER:** Today: snow flurries and light winds, temperature 20°F – 30°F. Tomorrow: snow with light winds, temperatures in the 20°F.

## UNIFIED COMMAND AND PERSONNEL:

Incident Commander: Jay Johnson, Alaska Petroleum Distributors SOSC: Steven Russell, ADEC FOSC: Robert Whittier, EPA Field SOSC: John Engles, ADEC

TIME/DATE OF THE NEXT REPORT DISTRIBUTION: As the situation warrants.

## FOR ADDITIONAL INFORMATION CONTACT:

Steven Russell, State on Scene Coordinator, ADEC (907) 262-3401.

or

http://dec.alaska.gov/spar/perp/



Alaska Petroleum Distributors trailer in Fairbanks yard Photo take 12/12/2014 by ADEC



Excavating contaminated soil from the road right-of-way Photo taken 12/21/2014 by RSE

## AGENCY/STAKEHOLDER NOTIFICATON LIST:

Please refer to the first sitrep distributed [date] for the agency/stakeholder notification list. The link to the first sitrep can be found in the **Additional Information** box above.