

555 Cordova Street
Anchorage, AK 99501
PHONE: (907) 269-7552
FAX: (907) 269-7649
<http://www.state.ak.us/dec/home.htm>

**DIVISION OF SPILL PREVENTION AND RESPONSE
CONTAMINATED SITES PROGRAM**

File No.: 2101.38.096
Database Reckey No.: 199421X120001

July 21, 2004

3 CES/CC
Attn: John Mahaffey
6326 Arctic Warrior Drive
Elmendorf AFB, AK 99506-3240

RE: ST409/7/9 Building 4913 Hospital, EC Contaminated Site Decision Documents,
Elmendorf Air Force Base, AK Dated April 23, 2004

Dear Mr. Mahaffey:

On April 26, 2004, the Alaska Department of Environmental Conservation (the Department) received several decision document packets. After reviewing the data and reports submitted for ST409/7/9, the Department agrees that no additional remediation or investigation is required for ST409/7/9 Database Reckey no. 199421X120001. Additional groundwater monitoring will be required until applicable cleanup levels in Table C of 18 AAC 75.345 are met.

The Base Master Plan needs to be updated to document the location of residual contamination at ST409/7/9 and the need to manage contaminated soil properly during any future construction or excavation work. The Department reserves its rights, under: 18 AAC 75 Contaminated Site regulations, 18 AAC 78 Underground Storage Tank regulations, and AS 46.03 to require additional investigation, cleanup, containment, and/or other necessary actions, if subsequent information indicates: additional contamination remains at the site which was previously undiscovered and presents an unacceptable risk to human health, safety, or welfare, or the environment.

If you have any questions regarding this letter, please call me at (907) 269-7552.

Sincerely,

Louis Howard
Project Manager
Federal Facilities Section