

To R. Williams
246-7630

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Spill Prevention and Response
Prevention and Emergency Response Program

SITUATION REPORT

INCIDENT NAME: Woodbine Cannery Gasoline

SITREP #: 1 and final

SPILL #: 01269911401

LEDGER CODE #: N/A

TIME AND DATE OF REPORT: April 15, 2001

TIME AND DATE OF NEXT REPORT: N/A

DRAFT

LOCATION: Woodbine Cannery , Egegik Alaska

TYPE AND AMOUNT OF PRODUCT SPILLED: Estimated 400 gallons unleaded regular gasoline

CAUSE OF SPILL: Spilt in 2" line between tank farm and dock

TIME AND DATE OF SPILL: Discharge occurred overnight April 23 and April 24, 2001.

POTENTIAL RESPONSIBLE PARTY (PRP): Woodbine Cannery, P.O. Box 218, Egegik, Alaska 99579

CURRENT SITUATION: A split in a two inch steel underground line leading from the Woodbine Cannery's tank farm to the seawall on the Egegik River resulted in the discharge of about 400 gallons of regular unleaded gasoline to the soil between the tank farm and the Egegik River. The gasoline migrated to the bulkhead along the river and 6 foot by 20 foot sheen was observed by cannery personnel in the river about 1115 AM April 24th. The line had been shut in for the winter and was placed back into service on April 23rd in preparation for opening the cannery for the season. The line was immediately shut in and drained and sorbent boom, sorbent pads and pillow were placed in the river and on the mud adjacent to the bulkhead.. By 12:30 PM the entry of product into the river had terminated. No further sheens have been observed during the past two tidal cycles.

Numerous recovery pits were dug between the pipeline and a point about fifteen feet ahead of the bulkhead.. As of 9:00 PM April 24th, about 240 gallons of gasoline were recovered. No further flow into the pits occurred overnight.

The soils cleanup is complicated by the site also being a contaminated site from earlier diesel spills. The cannery had planned to resume cleanup of this site May 10th. They are now considering expediting the process and revising the cleanup plan to reduce extent of contamination from this discharge. The damage to the pipeline may have occurred during the soil cleanup last fall. Marks and bends in the pipe in the vicinity of the break indicate that it had been hooked by a back hoe and then set back down into the ground. Cleanup of this site will be closely coordinated with the Department's Contaminated Sites Program. .

FUTURE PLANS AND RECOMMENDATIONS: Monitor the cleanup through the cannery personnel. When the situation stabilizes the cleanup will be integrated with the existing cleanup under the contaminated sites program.

WEATHER: Wind were light and variable during the initial response.

UNIFIED COMMAND PERSONNEL:

Incident Commander: Mike Lee, Woodbine Cannery
F.O.S.C: Bill Hutmacher, CAPT USCG
S.O.S.C: Leslie Pearson, ADEC
Field S.O.S.C: Harry Young, ADEC

FOR ADDITIONAL INFORMATION CONTACT:

FOR ADDITIONAL INFORMATION CONTACT: Harry Young, (907) 269-7542

AGENCY/STAKEHOLDER NOTIFICATION LIST

AGENCY	NAME	Sent Via		Telephone	Facsimile
ADNR	Sam Means/Deborah Heebner	Email		269-8548	269-8913
ADEC	SITREP Distribution	Email		465-5252	465-5244
ADEC	Marti Early mearly@envircon.state.ak.us	Email		465-5009	465-5097
ADFG	Claudia Slater/Mark Fink	Email		267-2338	267-2464
DMVA/DES	Terry Smith	Fax		428-7035	428-7009
USEPA	Matt Carr	Fax		271-3616	271-3424
USCG-MSO/ANC	Captain Hutmacher	Fax		271-6700	271-6751
ADPS	Alaska State Troopers	Fax		428-7200	428-7204
ADEC/FCO	Dan Easton	Fax		465-5135	465-5177
BBNA	Susan L. Flensburg	Fax			842-5939
L & P Borough	Marv Smith	Fax		246-3421	246-6602
OTHER	NAME	Sent Via	Session/Interim	Telephone	Facsimile
Senate/Bethel	Lyman Hoffman	Fax	Bethel/Juneau	465-4453	465-4523
House/Bethel	Mary Kapsner		Bethel/Juneau	465-4942	465-4589