

### List of Devices with No Determination

As provided for in 18 AAC 50.077, ADEC approves wood-fired heating devices for sale within the Fairbanks Nonattainment area that are EPA certified and where the department has reviewed and accepted the underlying certification test results. ADEC has undertaken review of all devices on EPA's certified list as of May 15, 2020 but moving forward will perform reviews of newly certified devices upon request. The following devices have been EPA approved and appear in the EPA database, however a request for review must be received by ADEC before a review of the certification report will commence.

Only after the review and any potential deficiencies identified have been corrected and approved will a device be placed on the Approved Device Lists.

To request that ADEC begin the review process refer to bottom of the page for instructions. For additional information regarding the ADEC review process please visit: <https://dec.alaska.gov/air/burnwise/manufacturers-vendors/>

This list will be updated at least monthly. If your device is not listed, and is EPA certified, please contact [Steven.hoke@alaska.gov](mailto:Steven.hoke@alaska.gov).

| Cordwood Devices' Review                       |                                             |                                              |
|------------------------------------------------|---------------------------------------------|----------------------------------------------|
| Manufacturer                                   | Models                                      | AK List Status                               |
| Arada Stoves Ltd                               | Farrington 12                               | Report Deficiencies not addressed            |
| Arada Stoves Ltd.                              | Farrington 16                               | Report Deficiencies Not Addressed            |
| Blaze King Industries, Inc.                    | King KE40                                   | Report Deficiencies Not Addressed            |
| Blaze King Industries, Inc.                    | Sirocco SC25, Ashford AF25, Boxer 24 (BX24) | Report Deficiencies Not Addressed            |
| Enerco Group, Inc.                             | WS110                                       | Reviewed – Information Required for approval |
| FPI / Fireplace Products International Limited | F1150, I1150                                | Report Deficiencies Not Addressed            |
| FPI / Fireplace Products International Limited | F1500                                       | Report Deficiencies Not Addressed            |

|                                                   |                                                                                                                                                                                                                 |                                      |
|---------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
| FPI / Regency Fireplace Products                  | F3500                                                                                                                                                                                                           | Report Deficiencies<br>Not Addressed |
| FPI / Regency Fireplace Products                  | I2450M, HI2450M                                                                                                                                                                                                 | Report Deficiencies<br>Not Addressed |
| FPI / Regency Fireplace Products                  | I2500                                                                                                                                                                                                           | Report Deficiencies<br>Not Addressed |
| FPI                                               | Meridian                                                                                                                                                                                                        | No Review Request<br>Received        |
| Foyers                                            | Flair 34, Lumis 32 - Cast<br>Iron, Lumis 32 - Soapstone,<br>Regal 32 - Soapstone, Regal<br>32 - Cast Iron                                                                                                       | No Review Request<br>Received        |
| GHP Group                                         | Pleasant Hearth Medium<br>Wood Stove PH1800WS,<br>MWS-1800, WSL-1800-B,<br>WSL-1800, GWS-1800-B,<br>GWS-1800                                                                                                    | No Review Request<br>Received        |
| GHP Group                                         | Pleasant Hearth Large<br>Wood Stove GWS-2200,<br>GWS-2200-B, WSL-2200,<br>WSL-2200-B, LWS-2200,<br>WS-2200, WS-2200-B,<br>PH2200WS, PH2200WS-B,<br>SWS-2200, SWS-2200-B,<br>HWS-2200, HWS-2200-B,<br>PWS-2200-B | No Review Request<br>Received        |
| Hearth and Home Technologies                      | Pioneer-II-C, Northstar-C,<br>Constitution (C40-C),<br>WarmMajic-II                                                                                                                                             | No Review Request<br>Received        |
| Hearth and Home Technologies                      | QuadraFire 31M-ACC-C and<br>QuadraFire Discovery-II-C                                                                                                                                                           | Report Deficiencies<br>Not Addressed |
| Hearth and Home Technologies                      | Quadra Fire 43M-ACC-C,<br>43ST-ACC-C, Discovery-III-C                                                                                                                                                           | Report Deficiencies<br>Not Addressed |
| Hearth and Home Technologies                      | Intrepid FlexBurn 2115-CAT                                                                                                                                                                                      | Report Deficiencies<br>Not Addressed |
| Hearthstone Quality Home Heating<br>Products Inc. | Mansfield 8013                                                                                                                                                                                                  | No Review Request<br>Received        |
| Hearthstone Quality Home Heating<br>Products Inc. | Bari, Bari Plus 8171 Hybrid                                                                                                                                                                                     | Report Deficiencies<br>Not Addressed |

|                                                |                                                                                                                                                                                                    |                                   |
|------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|
| Hearthstone Quality Home Heating Products Inc. | Castleton 8031                                                                                                                                                                                     | Report Deficiencies Not Addressed |
| Hearthstone Quality Home Heating Products Inc. | Heritage 8024                                                                                                                                                                                      | Report Deficiencies Not Addressed |
| Hussong Manufacturing Co.                      | Kozy Heat Z42, Kozy Heat Albany                                                                                                                                                                    | Report Deficiencies Not Addressed |
| Innovative Hearth products                     | Montecito-B, Bainbridge (LVCFAR), WCT6920, WCT4920, WRT4920                                                                                                                                        | Report Deficiencies Not Addressed |
| Innovative Hearth products                     | S210AGL, C210TGL, C210AGL, T2100GL, WSX2021WS-B                                                                                                                                                    | Report Deficiencies Not Addressed |
| Innovative Hearth products                     | Ladera-D, WRT3920-B                                                                                                                                                                                | No Review Request Received        |
| J. A. Roby Inc.                                | Pioneer, Galileo, Score, Magellan, Hubble, Messenger, Apollo, Gemini, Spirit, Kepler, Kocher, Cocinera, Fornello, Kouzina, Kuchenka, Komfyr, Hubble(R), Apollo(R), Gemini(R), Spirit(R), Kepler(R) | No Review Request Received        |
| Jotul North America                            | F35                                                                                                                                                                                                | No Review Request Received        |
| Jotul                                          | F45 V2                                                                                                                                                                                             | Report Deficiencies Not Addressed |
| Jotul North America                            | F55V2                                                                                                                                                                                              | Report Deficiencies Not Addressed |
| Jotul North America (Jotul U.S.A., Inc.)       | F 500 V3                                                                                                                                                                                           | Report Deficiencies Not Addressed |
| Kuma Stove and Iron Works                      | K-250 Series, Ashwood LE, Wood Classic LE, Cambridge LE, Cascade LE                                                                                                                                | Report Deficiencies Not Addressed |
| MF Fire                                        | Catalyst                                                                                                                                                                                           | Report Deficiencies Not Addressed |
| MF Fire                                        | Nova                                                                                                                                                                                               | Report Deficiencies Not Addressed |

**Alaska Department of Environmental Conservation**  
Division of Air Quality

No Determination Device List  
Updated: 7-5-2022

|                                                |                                                                                                    |                                   |
|------------------------------------------------|----------------------------------------------------------------------------------------------------|-----------------------------------|
| MF Fire                                        | Nova 2                                                                                             | No Review requested               |
| Morso                                          | 6140 B, 6143 B, 6148 B, and 6170 B                                                                 | Report Deficiencies Not Addressed |
| Morso Jernstoberi A/S                          | 1410B, 1440B, and 1450B                                                                            | Report Deficiencies Not Addressed |
| Morso Jernstoberi A/S                          | 2B Standard 2020                                                                                   | Report Deficiencies Not Addressed |
| Morso Jernstoberi A/S                          | 7110b                                                                                              | Report Deficiencies Not Addressed |
| Morso Jernstoberi A/S                          | 5660 B, 5660 B Standard                                                                            | No Review Request Received        |
| Nectre                                         | N65                                                                                                | No Review Request Received        |
| New Buck Corporation                           | 21 NC                                                                                              | Report Deficiencies Not Addressed |
| New Buck Corporation (Buck Stove Corp.)        | Model 81                                                                                           | No Review Request Received        |
| Pacific Energy Fireplace Products Limited      | FP30 LE, FP30AR LE                                                                                 | No Review Request Received        |
| Pacific Energy Fireplaces                      | FP25LE, FP25AR LE                                                                                  | Report Deficiencies Not Addressed |
| Pacific Energy Fireplace Products Limited      | Summit LE, Summit Classic LE, Alderlea T6 LE, and Summit Insert LE                                 | Report Deficiencies Not Addressed |
| Pacific Energy Fireplace Products Limited      | True North TN10                                                                                    | Report Deficiencies Not Addressed |
| Pacific Energy Fireplace Products Limited      | Vista LE, Vista Classic LE, NEO 1.6 LE, Neostone 1.6 LE, Alderlea T4 LE (Freestanding), NEO 1.6 LE | Report Deficiencies Not Addressed |
| Rais A/S                                       | Q-Tee II Steel, Q-Tee II Glass, and Q-Tee II C                                                     | Report Deficiencies Not Addressed |
| RSF / Industrial Chimney Company, Incorporated | Delta Fusion                                                                                       | Report Deficiencies Not Addressed |
| RSF / Industrial Chimney Company, Incorporated | Focus 320 SBR and Onyx SBR                                                                         | Report Deficiencies Not Addressed |
| RSF                                            | Pearl 3600, Perle 3600, Focus 3600, Focus 3600i, Focus 3600s                                       | No Review Request Received        |

|                                  |                                                                                                                                                                                                                |                                   |
|----------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|
| Sierra Products Inc              | S2300 FS, S2300 PB                                                                                                                                                                                             | No Review Request Received        |
| Sierra Products Inc              | S8000II TEC                                                                                                                                                                                                    | No Review Request Received        |
| Spartherm                        | Spartherm M 700 Insert,<br>Spartherm M 700 ZC,<br>Spartherm M 700 Module                                                                                                                                       | Report Deficiencies Not Addressed |
| Spartherm                        | Spartherm S 600 Insert,<br>Spartherm S 600 ZC,<br>Spartherm S 600 Module                                                                                                                                       | Report Deficiencies Not Addressed |
| Stove Builder International Inc. | 2.5 Series, Solution 2.5 ZC II,<br>Stratford II, FP10 Lafayette II,<br>FP12 Mundo II, Monaco II,<br>HE250R, Destination 2.7,<br>and Matrix 2700                                                                | Report Deficiencies Not Addressed |
| Stove Builder International Inc. | 3.3 Series Osburn 3300,<br>Austral III, Myriad III,<br>Legend III, Escape 1900,<br>Black Stag II, Solution 3.3,<br>Gateway 3300                                                                                | Report Deficiencies Not Addressed |
| Stove Builders International     | 1.7 Series - Archway 1700,<br>Gateway 1700, Columbia II,<br>Savannah II, Deco II,<br>HEI170, HES170, FW2800                                                                                                    | Report Deficiencies Not Addressed |
| Stove Builders International     | 1.7 Series - Blackcomb II,<br>Harmony 1.7, Solution 1.7,<br>Osburn 1700, Inspire 1700,<br>Escape 1500, Escape 1500-I,<br>Solution 1.7-I, Destination 1.7-I,<br>Osburn 1700-I, Matrix 1700-I,<br>Inspire 1700-I | Report Deficiencies Not Addressed |
| Stove Builders International     | XTD 1.9 Stove, XTD 1.9-I<br>Insert, CW2900 Insert,<br>Destination 2.3-I Insert, HEI 240<br>Insert, HEI 240R Insert,<br>Matrix-I, HES240, HEI240                                                                | No Review Request received        |
| Stove Builders International     | 1.4 Series (Osburn 950,<br>Escape 1200, Gateway 1400,<br>Solution 1.4, Spark II,                                                                                                                               | No Review Request received        |

|                              |                                                                                                      |                                   |
|------------------------------|------------------------------------------------------------------------------------------------------|-----------------------------------|
|                              | Fox, Déco Nano, S250, Harmony 1.4, and HES140)                                                       |                                   |
| Stove Builders International | 2.1 Series (Destination 1.9, Matrix 1900, CW2100, Green Mountain Insert 50, HEI90, and Archway 1500) | No Review Request received        |
| STUV AMERICA Inc.            | 30 Compact, 30 Compact-H, 30 Compact-one                                                             | Report Deficiencies Not Addressed |
| Stuv America, Inc.           | STUV 1658IN, STUV 1658CUBE, STUV 1658H, STUV 1658-Z                                                  | Report Deficiencies Not Addressed |
| Stuv America, Inc.           | Six 66-50                                                                                            | No Review Request received        |
| Stuv America, Inc.           | STUV SIX 76-55                                                                                       | No Review Request received        |
| Stuv America, Inc.           | STUV SIX 76-60                                                                                       | No Review Request received        |
| Travis Industries            | Answer                                                                                               | Report Deficiencies Not Addressed |
| Travis Industries            | Answer NexGen Hybrid                                                                                 | No Review Request received        |
| United State Stove Company   | US1100E, VG1120, AW1120E, CH11, NM680, SW1.2, and AHWS1120                                           | Report Deficiencies Not Addressed |
| United State Stove Company   | US1269E                                                                                              | Report Deficiencies Not Addressed |
| United State Stove Company   | US2000E, VG2020, AW2020E, CH20, NM890, SW2.0, and AHWS2020                                           | Report Deficiencies Not Addressed |
| United State Stove Company   | US2500E, AW2520E, VG2520, CH25, NM1190, SW2.5, and AHWS2520                                          | Report Deficiencies Not Addressed |
| United States Stove Company  | TR007E, US3200E VG3200, AW3200E                                                                      | Report Deficiencies Not Addressed |
| United States Stove Company  | US2941EB, VG4020, AW40, AW40E                                                                        | Report Deficiencies Not Addressed |

|                                   |                                                                    |                                      |
|-----------------------------------|--------------------------------------------------------------------|--------------------------------------|
| Vermont Castings                  | Vermont Castings Encore<br>2040-CAT-C                              | Report Deficiencies<br>Not Addressed |
| Wolf Steel Ltd.                   | NZ3000H, TZ3000H                                                   | No Review Request<br>Received        |
| Wolf Steel Ltd.                   | Napoleon S25, Napoleon<br>S25i, Timberwolf T25,<br>Timberwolf T25i | No Review Request<br>Received        |
| Wolf Steel Ltd.                   | Napoleon S30, Timberwolf<br>T30                                    | No Review Request<br>Received        |
| Woodstock Soapstone               | 205 Fireview Catalytic                                             | Report Deficiencies<br>Not Addressed |
| Woodstock Soapstone Company       | 202 Palladian, 204 Keystone                                        | Report Deficiencies<br>Not Addressed |
| Woodstock Soapstone Company       | 209a Progress Hybrid                                               | Report Deficiencies<br>Not Addressed |
| Woodstock Soapstone Company, Inc. | 210a Ideal Steel Hybrid                                            | Report Deficiencies<br>Not Addressed |

| Pellet Devices' Review           |                                                                         |                                   |
|----------------------------------|-------------------------------------------------------------------------|-----------------------------------|
| Manufacturer                     | Models                                                                  | Status                            |
| American Energy Systems<br>(AES) | 3500P, 35001, and 3502                                                  | Report Deficiencies Not Addressed |
| American Energy Systems<br>(AES) | Little Rascal                                                           | Report Deficiencies Not Addressed |
| American Energy Systems<br>(AES) | Magnum Baby<br>Countryside                                              | Report Deficiencies Not Addressed |
| APR Industries Ltd.              | Previa                                                                  | Report Deficiencies Not Addressed |
| ARDISAM, Inc.                    | Serenity Castle                                                         | Report Deficiencies Not Addressed |
| Enerco Group, Inc.               | PS130W                                                                  | Report Deficiencies Not Addressed |
| Enerco Group, Inc.               | PS20W                                                                   | Report Deficiencies Not Addressed |
| Enerco Group, Inc.               | PSBF66W                                                                 | Report Deficiencies Not Addressed |
| England Stove Works Inc          | 25CAB80, 55-SHPCAB80,<br>55-TRPCAB80, 55-<br>SHPCAB80S, 55-<br>RPCAB80S | Report Deficiencies Not Addressed |
| England Stove Works Inc          | 25-CB120, 55-<br>SHPCB120, 55-<br>TRPCB120                              | Report Deficiencies Not Addressed |
| England Stove Works Inc          | 25-CBEP, 55-SHPCBEP,<br>55-TRPCBEP                                      | Report Deficiencies Not Addressed |

**Alaska Department of Environmental Conservation**  
Division of Air Quality

No Determination Device List  
Updated: 7-5-2022

|                                                |                                                       |                                                |
|------------------------------------------------|-------------------------------------------------------|------------------------------------------------|
| England's Stove Works, Inc.                    | 25-CBPAH, 55-SHPCBPAH, and 55-TRPCBPAH                | Report Deficiencies Not Addressed              |
| England Stove Works Inc                        | 25-PDVC, 25-PDVCH, 55-SHP10, 55-SHP10L, and 55-TRP10  | Report Deficiencies Not Addressed              |
| Even Temp, Inc.                                | Eclipse                                               | Expired Report awaiting new report from retest |
| Even Temp, Inc.                                | Hastings                                              | Expired Report awaiting new report from retest |
| Even Temp, Inc.                                | Prescott EXP                                          | Expired Report awaiting new report from retest |
| Even Temp, Inc. - St Croix Product Development | Prescott II EXP and Prescott II EXL                   | No Review Request Received                     |
| Gruppo Piazzetta S.P.A.                        | LIA, LISA                                             | Report Deficiencies Not Addressed              |
| Gruppo Piazzetta SPA                           | Sabrina 2.0, Sally 2.0, Solange 2.0, Sveva 2.0        | Report Deficiencies Not Addressed              |
| Hearth and Home Technologies                   | ECO Choice PS35-C, Quadra-Fire PS35-C                 | Report Deficiencies Not Addressed              |
| Hearth and Home Technologies                   | PH50PS-B, PH50CABPS-B                                 | Report Deficiencies Not Addressed              |
| Hearth and Home Technologies                   | Harman Absolute 63                                    | Report Deficiencies Not Addressed              |
| Hearth and Home Technologies                   | Harman Accentra 52i-TC                                | Report Deficiencies Not Addressed              |
| Hearth and Home Technologies                   | Harman Accentra-2                                     | Report Deficiencies Not Addressed              |
| Hearth and Home Technologies                   | Harman Allure 50                                      | Report Deficiencies Not Addressed              |
| Hearth and Home Technologies                   | Harman P43-C                                          | Report Deficiencies Not Addressed              |
| Hearth and Home Technologies                   | PelPro PPC90, PelPro TSC90, and Pleasant Hearth PHC90 | Report Deficiencies Not Addressed              |
| Hearth and Home Technologies                   | Quadra-fire Classic Bay 1200I-C                       | Report Deficiencies Not Addressed              |
| Heat Tech Industries, LLC.                     | HTP 26 Bay, HTP26 Bay Pedestal/Insert                 | Report Deficiencies Not Addressed              |
| Heat Tech Industries, LLC.                     | HTP 26 Standard                                       | Report Deficiencies Not Addressed              |
| Innovative Hearth Products                     | Winslow PI40GL, Winslow PS40GL                        | No Review Request Received                     |
| Liberator Rocket Heaters                       | RMH-2                                                 | No Review Request Received                     |

**Alaska Department of Environmental Conservation**  
Division of Air Quality

No Determination Device List  
Updated: 7-5-2022

|                                                            |                                                                                                          |                                   |
|------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|-----------------------------------|
| LMF Manufacturing Ltd<br>dba America's Heat                | America's Heat B-100                                                                                     | Report Deficiencies Not Addressed |
| Ravelli                                                    | Monica 2015, Francesca<br>2015, RV80 CERAMICA                                                            | Report Deficiencies Not Addressed |
| Ravelli                                                    | Roma                                                                                                     | Report Deficiencies Not Addressed |
| Ravelli SRL                                                | RV100 Classic                                                                                            | Report Deficiencies Not Addressed |
| Ravelli                                                    | RV120 Touch                                                                                              | Report Deficiencies Not Addressed |
| SBI                                                        | Osburn                                                                                                   | Report Deficiencies Not Addressed |
| Sherwood Industries Ltd<br>dba Enviro                      | Meridian-1, FPI, Cast<br>Iron, GF55, GF155                                                               | Report Deficiencies Not Addressed |
| Sherwood Industries Ltd<br>dba Enviro                      | Enviro - Meridian-2,<br>Meridian FPI-2,<br>Meridian Cast Iron-2,<br>Regency Greenfire<br>GF55-2, GF155-2 | No Review Request Received        |
| Sherwood Industries Ltd<br>dba Enviro                      | Enviro Mini 2, Enviro P3-<br>2 Regency Greenfire<br>GF40-2                                               | No Review Request Received        |
| Sherwood Industries Ltd<br>dba Hudson River Stove<br>Works | EF2-1, Chatham-1,<br>Davenport-1, and<br>Kinderhook-1                                                    | Report Deficiencies Not Addressed |
| Sierra Product, Inc.                                       | EasyFire Pellet Stove,<br>EF3801, EF5001, EF4001                                                         | Report Deficiencies Not Addressed |
| SMG Hearth & Home dba<br>Comfortbilt                       | ComfortBilt HP22N,<br>HP22, and HP22i Insert                                                             | Report Deficiencies Not Addressed |
| SMG Hearth & Home dba<br>Comfortbilt                       | HP21                                                                                                     | Report Deficiencies Not Addressed |
| SMG Hearth & Home dba<br>Comfortbilt                       | HP54                                                                                                     | Report Deficiencies Not Addressed |
| SMG Hearth & Home dba<br>Comfortbilt                       | HP55                                                                                                     | Report Deficiencies Not Addressed |
| SMG Hearth & Home dba<br>Comfortbilt                       | HP61                                                                                                     | Report Deficiencies Not Addressed |
| SMG Hearth and Home,<br>LLC                                | ComfortBilt HP50S                                                                                        | No Review Request Received        |
| Sun Mountain Stove<br>Works Inc.                           | Whitney                                                                                                  | No Review Request received        |
| Thelin Company Inc.                                        | Echo-Comstock II                                                                                         | No Review Request Received        |
| Thelin Company Inc.                                        | Providence                                                                                               | No Review Request Received        |
| Thermorossi                                                | Slimquadro 11                                                                                            | Report Deficiencies Not Addressed |
| Thermorossi                                                | Slimquadro 9                                                                                             | Report Deficiencies Not Addressed |

|                             |                                                                                                                                            |                                   |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|
| United States Stove Company | GW1949, AP77, SW1117                                                                                                                       | Report Deficiencies Not Addressed |
| United States Stove Company | KP5513, KP5513-P, KP5513-L, US5513, US5513-P, US5513-L, AP5613, AP5613-P, AP5613-L, VG5713, VG5713-P, VG5713-L, Little E (SP500), 5501S-XH | Report Deficiencies Not Addressed |
| United States Stove Company | 5710, AP5710, VG5710, 5501S, AP5501S, VG5501S                                                                                              | Report Deficiencies Not Addressed |
| United States Stove Company | 5780-E, AP5780-E, VG5780-E, SP5780-E, SP58-E                                                                                               | Report Deficiencies Not Addressed |
| United States Stove Company | 5780, AP5780, VG5780, SP5780, and SP58                                                                                                     | Report Deficiencies Not Addressed |

| Hydronic Pellet Devices' Review              |                     |                                   |
|----------------------------------------------|---------------------|-----------------------------------|
| Manufacturer                                 | Models              | Status                            |
| Fröling Heizkessel und Behälterbau Ges.m.b.H | PE1 Pellet 20       | Report Deficiencies Not Addressed |
| Fröling Heizkessel und Behälterbau Ges.m.b.H | PE1 Pellet 35       | Report Deficiencies Not Addressed |
| Hargassner GmbH                              | ECO-HK 70 Multifuel | Report Deficiencies Not Addressed |

**The above listed devices will not be reviewed without a formal request. In order to get a specific device reviewed follow the steps outlined below.**

1. Send an email to [steven.hoke@alaska.gov](mailto:steven.hoke@alaska.gov)
2. Request that device be reviewed for inclusion in the Approved Device List
3. Identify device name.
4. Identify report number.
5. Device must be on EPA certified list.
6. Provide publicly available link of report for device.
7. The review process will take several weeks depending on the number of reviews currently being conducted.
8. Once review is completed, a copy of the summary report will be sent to Manufacturer for review. Report will be posted on the Manufacturer page after approximately 45 days unless errors or corrections are identified. Once complete, the summary report will be

posted even if final determination is pending – minor or major, or disapproved. If final determination is pending, major or minor, the device will remain on this Pending Review with the Pending in the status column and will not be placed on the Approved List, until Pending items are addressed.

9. Until a final determination of Approved is made, the status column on the Pending Review List will be updated and used to indicate where in the review process the device's certification test is at.
  - a. No Request Received
  - b. Request Received [Date]
  - c. Reviewed-Information Required for approval
  - d. Report Deficiencies Not Addressed

Note: If final determination is Approved, the device will be removed completely from this list and placed on the Approved List.