ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Spill Prevention and Response Prevention and Emergency Response Program

SITUATION REPORT

INCIDENT NAME: F/V Donna Ann

SITREP #: 2 and final

SPILL NUMBER: 03239923202

LEDGER CODE: 14113660

<u>TIME/DATE OF SPILL</u>: U.S. Coast Guard reported to ADEC that the vessel grounded at 2:40 a.m., August 20, 2003.

TIME/DATE OF SITUATION REPORT: 4:00 p.m., August 21, 2003

TIME/DATE OF THE NEXT REPORT: This is the final report

<u>**TYPE/AMOUNT OF PRODUCT SPILLED**</u>: The vessel owner reported 1000 gallons of diesel was on board the vessel at the time of the grounding. Further gauging of fuel tanks on August 22^{nd} found no fuel in the tanks.

LOCATION: Tanglefoot Bay, Karluk, on Kodiak Island

<u>CAUSE OF SPILL</u>: F/V Donna Ann, a 58' wooden hulled vessel, drifted aground on a gravel and sand beach after dragging anchor in Tanglewood Bay at 2:40 a.m. on August 20.

POTENTIAL RESPONSIBLE PARTY (PRP): Owner of F/V Donna Ann, David W. Johnson

<u>RESPONSE ACTION</u>: ADEC and U.S. Coast Guard staff performed an overflight of the grounding site this afternoon. No sheening was observed during that overflight. ADEC and Coast Guard spill responders landed at the site, met with the vessel owner, and performed a beach assessment. They did not find any fuel contamination on the beach or high tide lines. It is assumed the vessels diesel fuel was dispersed during yesterday's storm.

The vessel owner is currently trying to collect debris that had been torn from the vessel during yesterday's storm.

SOURCE CONTROL: The vessel owner will make an attempt to remove a small amount of hydraulic fluid remaining on the vessel.

<u>RESOURCES AFFECTED</u>: No shoreline contamination observed during shoreline assessment at low water today. No impacted wildlife was reported or observed during shoreline assessment.

<u>FUTURE PLANS AND RECOMMENDATIONS</u>: The vessel owner will continue to collect debris from the vessel. The vessel owner is also looking for assistance in removing the vessel from the beach. ADEC and U.S Coast Guard representatives activated for the response will be returning to their home base. ADEC shall coordinate with ADNR to preclude unresolved abandoned vessel concerns.

WEATHER: Temperature 59 degrees F., Wind: SW 5 mph, Seas: 1-2 foot.

UNIFIED COMMAND AND PERSONNEL:

Incident Commander:	Captain Morris, USCG
F.O.S.C.:	Captain Morris, USCG
S.O.S.C.:	Gary Folley, ADEC
Field S.O.S.C.:	Jace Johnson, ADEC

FOR ADDITIONAL INFORMATION CONTACT: John Brown, ADEC, phone: 907-269-7688.

AGENCY	NAME	Sent Via		Telephone	Facsimile
ADNR	Clark Cox	Email	Clark_Cox@dnr.state.ak.us	269-8565	269-8913
ADEC	Field Office, Kodiak EH	Email		486-3350	486-5032
USCG-MSD/KOD	Lt. Danielle Wiley	Fax		486-5918	487-5585
USCG-MSO/ANC	Captain Morris	Fax		271-6700	271-6751
US EPA	Matt Carr/Carl Lautenberger	Fax		271-3616	271-3424
OTHER	NAME	Sent Via		Telephone	Facsimile
PWS RCAC	John Devens	Fax		835-5957	835-5926
CIRCAC	Mike Munger	Fax/Email	munger@circac.org	283-7222	283-6102
City of Kodiak	Linda Freed, City Manager	Fax		486-8640	486-8600
Kodiak Is. Borough	Michelle Stearns	Fax		486-9360	486-9396
			Session/Interim		
House 36/Kodiak	Dan Ogg	Fax	Kodiak 5/16 - 1/09	486-8872	465-5264
			Juneau 1/10 - 5/15	465-2487	465-4956
Senate R/Kodiak	Gary Stevens	Fax	Juneau 5/16 - 1/09	486-4925	486-3517
			Juneau 1/10 - 5/15	465-4925	465-3517



F/V Donna Ann aground on pebble gravel beach. ADEC photograph