

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Spill Prevention and Response
Prevention and Emergency Response Program

SITUATION REPORT

INCIDENT NAME: EAFB Product Recovery Tank Spill **SITREP #:** 1

SPILL NUMBER: 04239904301

LEDGER CODE: Requested

TIME/DATE OF SPILL: 12:08 AM, February 12, 2004, EAFB contacted trooper dispatch at 3:32 AM, February 12, 2004.

TIME/DATE OF SITUATION REPORT: 2:00 PM, February 12, 2004,

TIME/DATE OF THE NEXT REPORT: 12:00 PM, February 13, 2004

TYPE/AMOUNT OF PRODUCT SPILLED: JP-8 Jet Fuel, a kerosene-based fuel, EAFB estimates 8814 gallons spilled.

LOCATION: West Ramp Pumphouse Building 13196, EAFB

CAUSE OF SPILL: Currently under investigation by EAFB and ADEC's PERP and Industry Preparedness and Prevention Program.

POTENTIAL RESPONSIBLE PARTY (PRP): Elmendorf Air Force Base

RESPONSE ACTION: ADEC responders from PERP and IPPP met with Elmendorf Air Force Base (EAFB) fire department and Civil Engineering spill team leads at approximately 8:30 AM this morning. Jet fuel had migrated to a surface depression. EAFB had deployed absorbent boom to contain the fuel spill in this area preventing the migration of fuel and ultimately aiding free product recovery efforts

EAFB hired Emerald Services of Alaska (Emerald) to assist in the response and recovery effort. EAFB and Emerald vacuum and fuel recovery trucks have recovered about 500 gallons of free product. The mechanical and manual removal of contaminated snow will be initiated today along with fuel recovery operations. Emerald will transport contaminated snow to their facility and stockpile it within lined containment. Emerald will then process the snow, recovering fuel and properly disposing of associated melt water.

SOURCE CONTROL: EAFB manually activated the emergency shut down at the pumphouse after the supply fuels control center indicated an overfill at the product recovery tank. The fuel trucks are not to be loaded until a diagnostic has been run on the system.

RESOURCES AFFECTED: Gravel pad, fuel covered approximately 1,000 square feet of gravel surface outside the pumphouse.

FUTURE PLANS AND RECOMMENDATIONS: EAFB hired Western Solutions to delineate and remove contaminated soils after removal of snow and ice is completed. Staffs from ADEC IPPP are to coordinate with EAFB to ensure appropriate prevention measures are implemented as necessary.

WEATHER: Clear and calm, 20 degrees F.

UNIFIED COMMAND AND PERSONNEL:

Incident Commander:	John Mahaffey, Civil Engineering Squadron
F.O.S.C. :	
S.O.S.C. :	Gary Folley
Field S.O.S.C.:	Harry Young

FOR ADDITIONAL INFORMATION CONTACT: Frank Wesser @ 907- 269-7542.

AGENCY/STAKEHOLDER NOTIFICATION LIST

AGENCY	NAME	Sent Via		Telephone	Facsimile
ADNR	Clark Cox	Email	Clark_Cox@dnr.state.ak.us	269-8565	269-8913
ADOT-AIA	Monique Garbowicz	Fax/Email		266-2129	266-2622
Dept of Law	Craig Tillery	Email	craig_tillery@law.state.ak.us	269-5275	278-7022
DMVA/DES	Terry Smith	Fax		428-7035	428-7009
EAFB	John Mahaffey	Fax/Email	MahaffeyJ@elmendorf.af.mil	552-7415	552-1533
USCG-MSO/ANC	Captain Morris	Fax		271-6700	271-6751
US EPA	Matt Carr/Carl Lautenberger	Fax		271-3616	271-3424
OTHER	NAME	Sent Via		Telephone	Facsimile
CIRCAC	Mike Munger	Email	munger@circac.org	283-7222	283-6102
Cook Inlet Keeper	Bob Shavelson	Email	Bob@inletkeeper.org	235-4068	235-4069
Muni. of Anch.	Tracy Matthews	Fax		343-1401	343-1441
Gov't. Hill Comm. Council	Kathleen Gerlek	Fax		277-0398	
Mnt. View Comm. Council	Randy Smith	Fax		272-4672	272-1247
			Session/Interim		
House18/Anchorage	Nancy Dahlstrom	Fax	Eagle River 5/16 - 1/09 Juneau 1/10 - 5/15	622-3783 465-3783	622-3784 465-2293
Senate1/Anchorage	Fred Dyson	Fax	Eagle River 5/16 - 1/09 Juneau 1/10 - 5/15	694-6683 465-2199	694-1015 465-4587



EAFB Fuel Recovery of Jet Fuel with vacuum truck.