

**ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION**  
**Division of Spill Prevention and Response**  
**Prevention and Emergency Response Program**

**SITUATION REPORT**

**INCIDENT NAME:** Tesoro Fuel Transfer Line

**SITREP #:** 1

**SPILL NUMBER:** 06239918001

**LEDGER CODE:** Requested

**TIME/DATE OF SPILL:** The discharge was discovered on July 19, 2006 during an annual pressure test of 10-inch fuel transfer line that is 1,900 feet in length between Tesoro's Anchorage Terminal 1 and the Port of Anchorage valve yard. The PRP reported the discharge to ADEC at 7:13 PM on July 19, 2006.

**TIME/DATE OF SITUATION REPORT:** 3:00 PM, July 21, 2006

**TIME/DATE OF NEXT REPORT:** 1:00 PM, July 24, 2006

**TYPE/AMOUNT OF PRODUCT SPILLED:** The line is a low-pressure jet and diesel fuel transfer line. Currently, amount of product spilled is unknown.

**LOCATION:** 1601 Tidewater Road, Port of Anchorage

**CAUSE OF SPILL:** The PRP reported indication of a leak as a result of pressure testing. The cause and the source of the leak are currently being investigated.

**POTENTIAL RESPONSIBLE PARTY (PRP):** Tesoro Corporation

**RESPONSE ACTION:** On July 20th, the PRP commenced excavation to expose a section of the transfer line to investigate the possible leak. On July 21st, the PRP started removing pavement north of the excavated area to investigate another section of the line. A more refined excavation is being completed around the transfer line by response personnel using hand tools.

Response personnel are also monitoring a storm water manhole, west of the transfer line, which is currently accumulating a light sheen. It is unclear if the sheen is associated with the transfer line leak.

**SOURCE CONTROL:** The delivery line has been shut down for the investigation.

**RESOURCES AFFECTED:** No impacts to wildlife or other resources have been reported.

**FUTURE PLANS AND RECOMMENDATIONS:** The PRP will continue to excavate the transfer line to determine the leak source. An ADEC responder will be on site to monitor the field activities.

**WEATHER:** Mostly cloudy with isolated showers. Scattered showers along the Turnagain Arm. Highs in the mid 60s to lower 70s. Winds South 10 to 20 mph.

**UNIFIED COMMAND AND PERSONNEL:**

Incident Commander	Shawn Brown, Tesoro Corporation
F.O.S.C.	Mark DeVries, Captain, USCG
S.O.S.C.	Gary Folley, ADEC
Field S.O.S.C.	John Brown, ADEC


**FOR ADDITIONAL INFORMATION CONTACT:**

ADEC S.O.S.C	Gary Folley, 398-4368
ADEC Field S.O.S.C	John Brown, 269-7688
Tesoro Corporation Public Affairs	Kip Knudson, 382-0219
U.S. Coast Guard Public Affairs	Sarah Francis, 321-4510

**AGENCY/STAKEHOLDER NOTIFICATION LIST**

This sitrep has been distributed via email to the Governor’s office, ADF&G, ADNR, SECC, USEPA, USDOJ, NMFS, USFWS, and USFS in addition to the following.

AGENCY	NAME	Sent Via		Telephone	Facsimile
Dept Law	Craig Tillery	Email	craig_tillery@law.state.ak.us	269-5275	278-7022
USCG-MSO/ANC	MSO/Anchorage Office	Fax		271-6700	271-6751
US EPA	Matt Carr	Fax		271-3616	271-3424
OTHER	NAME	Sent Via		Telephone	Facsimile
CIRCAC	Mike Munger	Fax/Email	munger@circac.org	283-7222	283-6102
Port of Anchorage/Muni	Bill Sheffield	Fax	sheffieldwi@muni.org	343-6200	277-5636
Tesoro Alaska	John Kwietniak	Email	jkwietniak@tsocorp.com		776-3812
			<b>Session/Interim</b>		
<b>House 23</b> /Anchorage	Les Gara	Fax	Anchorage 5/16 - 1/09 Juneau 1/10 - 5/15	269-0106 465-2647	269-0109 465-3518
<b>Senate L</b> /Anchorage	Johnny Ellis	Fax	Anchorage 5/16 - 1/09 Juneau 1/10 - 5/15	269-0169 465-3704	269-0172 465-2529



**Figure 1:** Area location map, Port of Anchorage.