



THE STATE  
of **ALASKA**  
GOVERNOR MIKE DUNLEAVY

Department of Environmental  
Conservation

DIVISION OF SPILL PREVENTION AND RESPONSE  
Prevention, Preparedness, and Response Program

410 Willoughby Avenue, Suite 303  
P.O. Box 11800  
Juneau, AK 99811-1800  
Main: 907-465-5250  
Fax: 907-465-5245  
[www.dec.alaska.gov](http://www.dec.alaska.gov)

February 10, 2023

Christina Bentz  
NorthStar Energy  
509 West 3<sup>rd</sup> Ave, Suite 101  
Anchorage, AK 99501

Subject: **Delta Western Diesel Overfill 130 3<sup>rd</sup> St JNU, Spill #: 22119902801, No Further Action**

Dear Ms. Bentz:

The Alaska Department of Environmental Conservation (department) has completed its review of the case file for the above referenced spill including the Field Screening and Sampling Report, prepared by Environmental Management, Inc. on December 20, 2022, and the ADEC Final Report Form, prepared by Northstar Energy on June 10, 2022. These reports summarize the cleanup actions taken, including free product recovery with sorbent material, spill site characterization, and proper disposal of oiled sorbent material. The analytical results from the site characterization indicate that there are no petroleum hydrocarbon related analytes present above the Human Health and Maximum Allowable Concentrations in the vicinity of the aboveground storage tank or along the potential path of diesel impacts.

The scope of the Field Screening and Sampling Report was limited to the characterization of impacts from the December 20, 2022, overfill. It should be noted that all analytical samples were taken from a depth of 0.5-feet below ground surface. Environmental Management, Inc noted that at greater depths, there was evidence that suggests potential impacts from other pre-existing spills, for which Delta Western is not the presumed responsible party. This is consistent with information found in the department's Contaminated Sites Database (Hazard ID: 3857) which shows sub-surface soil contamination remaining at 123 4<sup>th</sup> Street.

Based on the information in the aforementioned reports and records review, the department has determined that the lowest practicable level of contamination has been achieved under 18 AAC 75.315 and no further containment or cleanup is required for this site at this time.

If additional areas or levels of contamination are discovered in the future that are not included in the information submitted to the department, you are required under 18 AAC 75 to contact this office at 907-465-5340. In addition, cost recovery under Alaska Statute 46.08.070 will continue until all state costs have been reimbursed.

If you have questions or comments regarding this matter, please contact me at 907-465-5204 or Chris.Salazar@alaska.gov.

Sincerely,

DocuSigned by:  
*Chris Salazar*  
34E3D633DFB5406...

Chris Salazar  
Environmental Program Specialist

cc:

Rachael Krajewski, ADEC  
Cost Recovery, ADEC  
Evonne Reese, ADEC  
Anne Palmieri, ADEC