



ID	Location and Description	Response Strategy	Implementation	Response Resources	Staging Area	Site Access	Resources Protected (months)	Special Considerations
K-47-01 	Seal Bay Nearshore waters in the general area of: Lat. 58° 22.1 N Lon. 152° 12.1 W	Free-oil Recovery Maximize free-oil recovery in the offshore & nearshore environment of Seal Bay depending on spill location and trajectory.	Deploy free-oil recovery strike teams upwind and up current of Seal Bay. Use aerial surveillance to locate incoming slicks.	Deploy multiple free-oil recovery strike teams as required to maximize interception of oil before it impacts sensitive areas.	Kodiak/Homer/ Kitoi Bay Hatchery	Via marine waters Chart 16604-1	Same as K-47-02	Vessel master should have local knowledge. Use extreme caution, shoal waters with numerous reefs and rocks.
K-47-02 	Seal Bay a. Lat. 58° 21.05 N Lon. 152° 14.67 W b. Lat. 58° 21.09 N Lon. 152° 15.66 W	Exclusion Exclude oil from impacting the identified stream and intertidal area in Seal Bay.	Deploy anchors and boom with skiffs (class 6). For (a) place 50 ft. tidal-seal on the western shore and complete with 1000 ft. protected-water boom. For (b) place 100 ft. tidal-seal and complete with 400 ft. protected-water boom. Tend throughout the tide.	Deployment Equipment 1400 ft. protected-water boom 150ft. tidal-seal boom 8 ea. small anchor systems 8 ea. anchor stakes Vessels 1 ea. class 3 1 ea. class 6 Personnel/Shift 5 ea. vessel crew Tending Vessels 1 ea. class 3 1 ea. class 6 Personnel/Shift 3 ea. vessel crew	Vessel platform Afognak Wilderness Lodge located in Seal Bay may provide logistical support and lodging.	Via marine waters Chart 16604-1	Fish- intertidal spawning-herring (April-May0, salmon (May-Sept), dolly varden Birds-waterfowl concentration, seabird nesting, eagle nesting Human Use-Commercial fishing, subsistence, high recreational use Marine mammals- seals, otters Habitat-sheltered rocky shoreline, sheltered tidal flats	Vessel master should have local knowledge. FOSC Historic properties specialist should INSPECT site prior to operations. A large bear population exists in the area; bear guards may be necessary. Site surveyed: 7/24/05 KGRS Tactics Committee. Title 41 permitting required from ADNR. Tested: not yet