

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Spill Prevention and Response
Prevention and Emergency Response Program

SITUATION REPORT

INCIDENT NAME: M/V Hayden Bay Grounding

SITREP #: 3 & Final

SPILL NUMBER: 04119916801

LEDGER CODE: None Requested

TIME/DATE OF SPILL: 5:20 A.M., June 16, 2004. The incident was reported to ADEC by the US Coast Guard at 8:00 A.M., June 16, 2004

TIME/DATE OF SITUATION REPORT: 10:30 A.M., June 18, 2004

TIME/DATE OF THE NEXT REPORT: This is the final report.

TYPE/AMOUNT OF PRODUCT: Diesel fuel, unknown amount. The Responsible Party reported that the vessel has a 500 gallon capacity fuel tank. Minor sheens which quickly dissipated were reported at the time the vessel first sank and during the first refloat attempt. There were no sheens reported during the successful refloat operation.

LOCATION: Kah Shakes Cove, Misty Fjords National Monument, (Lat 55.029 N, 131 001 W), approximately 35 miles southeast of Ketchikan.

CAUSE OF INCIDENT: The M/V Hayden Bay, a 40 ft. fiberglass passenger vessel sank after running aground an unmarked rock. The two (2) people on board safely evacuated in a life raft. The individuals were picked up by the Coast Guard and taken to Ketchikan.

POTENTIAL RESPONSIBLE PARTY (PRP): Kurt Redd, Portland, Oregon

RESPONSE ACTION:

The salvor's initial attempt to refloat the vessel on June 17, 2004 was unsuccessful. The vessel was moved closer to shore and the second attempt to refloat the vessel was successful. The vessel was refloat at around 1:00 A.M. on June 18, 2004. The vessel was dewatered and a damage assessment survey revealed no holes or other significant damage to the hull. The vessel is currently being towed to Ketchikan and is estimated to arrive at around 11:30 A.M. this morning.

SOURCE CONTROL: The fuel vents have been plugged. All fuel and oils remain on board at this time.

RESOURCES AFFECTED: The vessel ran aground and sank in Kah Shakes Cove. There are no reports of injured wildlife or shoreline impacts due to the minor sheens observed.

FUTURE PLANS AND RECOMMENDATIONS:

Continue coordination with the Responsible Party and the Coast Guard to determine the cause of the grounding of the vessel.

WEATHER: Clear, 60-65 degrees, Winds and seas calm.

UNIFIED COMMAND AND PERSONNEL:

Incident Commander:	Carla Shown (PRP)
F.O.S.C.:	CDR. Sifling (USCG)
S.O.S.C.:	Bob Mattson (ADEC)
Field S.O.S.C.:	Bob Fultz, SART Ketchikan (ADEC)
On-Scene Commander:	Greg Updike, Alaska Commercial Divers

FOR ADDITIONAL INFORMATION CONTACT: Bob Fultz, ADEC, 225-6200

AGENCY/STAKEHOLDER NOTIFICATION LIST

Agency	Name	Sent Via	Additional Info	Telephone	Fax
ADNR	Doug Sanvik	Email	doug_sanvik@dnr.state.ak.us	465-3400	465-3513
ADF&G	Mark Fink	Email	Sent via Spill Report Group	267-2338	267-2464
USCG MSO	Cdr. John Sifling	Email	jsifling@cgalaska.uscg.mil	463-2453	463-2445
USCG (MSD Ketchikan)	Lt. Milo Ortiz	Email	mortiz@cgalaska.uscg.mil	225-4496	225-4499
	MSTC Jeff Prince	Email	JPrince@cgalaska.uscg.mil		
	MST1 Van Vu	Email	vvu@cgalaska.uscg.mil		
USFS	Jerry Ingersoll	Fax	Ketchikan District Ranger	228-4100	225-8738
EPA	Matt Carr	Email	Sent via Spill Report Group	271-3616	271-3424
NMFS	Jon Kurland	Email	Jon.kurland@noaa.gov	586-7638	586-7358
OTHER	NAME	Sent Via	Additional Info	Telephone	Fax
Responsible Party	Carla Shown	Fax	RP Representative	(503)289-2669	(503)289-2825
SEAPRO	Dave Owing	Email	dave@seapro.org	225-7002	247-1117
Senate/Dist. A	Sen. Bert Steadman	Fax	Session : Interim:	465-3873 225-8088	465-3922 225-5013
House/Dist. 1	Bill Williams	Fax	Session : Interim:	465-3424 247-4672	465-3793 225-8546
Metlakatla Indian Community	Mayor Victor Wellington	Fax		886-4441	886-7997
Village of Saxman	President Joe Williams	Fax		247-2502	247-2504
Ketchikan Indian Association	General Manager Mary Edenso	Fax		225-5158	247-0429
Ketchikan Borough	Mayor Mike Salazar	Fax		228-6625	247-6625



Photo 1. The *Hayden Bay* before being refloated. Photo courtesy USGC