

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Spill Prevention and Response
Prevention and Emergency Response Program

SITUATION REPORT

INCIDENT NAME: F/V Johnny A Sinking

SITREP #: 2

SPILL NUMBER: 05119920601

LEDGER CODE: Not currently assigned

TIME/DATE OF SPILL: The vessel sank at approximately 5:00 AM on July 25, 2005.

TIME/DATE OF SITUATION REPORT: 3:00 PM, July 27, 2005

TIME/DATE OF THE NEXT REPORT: As the situation warrants.

TYPE/AMOUNT OF PRODUCT SPILLED: The total amount of product spilled is unknown. A light sheen was reported to have been observed around the vessel immediately following the sinking, but no further release has been observed. Approximately 5000 gallons of diesel was on board the vessel at the time that it sank.

LOCATION: Whitestone Harbor, located approximately 13 miles east of Hoonah on Chichagof Island; 30 miles southwest of Juneau.

CAUSE OF SPILL: The 58' fishing seiner hit a rock on the way into the harbor and sank. The vessel is currently submerged but stable, with the bow in 70 feet of water. A U.S. Coast Guard casualty investigation has been initiated and is ongoing.

POTENTIAL RESPONSIBLE PARTY (PRP): John Hinchman, vessel owner. Robert James Day, Jr., vessel operator.

RESPONSE ACTION: The vessel's manager has contracted Southeast Alaska Lighterage (SEAL), to provide pollution response. A response plan has been submitted to the USCG and ADEC. To date, SEAL has been unable to begin recovery efforts due to adverse weather conditions. The contractor is en route to the site, and response actions are scheduled to begin today if the weather allows.

SOURCE CONTROL: All of the aft fuel vents have been sealed. The forward vents are located in the engine room and are inaccessible to divers.

RESOURCES AFFECTED: There have been no reports of oiled wildlife. Resources in the area include: commercial and sport fisheries in Whitestone Harbor and Chatham Strait; several species of shorebirds also inhabit nearby tide flats and marshes.

FUTURE PLANS AND RECOMMENDATIONS: A SEAL response vessel is en route to the site with recovery equipment. Their intent at this time is to refloat the vessel and move it to a nearby cove to facilitate safe recovery and better pollution control. They will then be able to soft patch and trim out the vessel prior to towing it to Auke Bay Harbor in Juneau. USCG and ADEC will continue to monitor the situation.

WEATHER: Currently 58° F, East winds 8 mph, seas 3-5 ft. Forecast: S Winds 10 knots. Seas 2 ft or less.

UNIFIED COMMAND AND PERSONNEL:

Incident Commander:	Jay Kaino, RP
F.O.S.C.:	Cdr. John Sifling, USCG
S.O.S.C.:	Bob Mattson, ADEC
Field S.O.S.C.:	Lester Leatherberry, ADEC

FOR ADDITIONAL INFORMATION CONTACT: Lester Leatherberry, ADEC, SART (907) 465-5349.

AGENCY/STAKEHOLDER NOTIFICATION LIST

This sitrep has been distributed via email to the Governor's office, ADF&G, ADNR, SECC, USEPA, USDOJ, NMFS, USFWS, and USFS in addition to the following.

Agency	Name	Sent Via	Additional Info	Telephone	Fax
USCG (MSO Juneau)	CDR John Sifling	Email	jsifling@cgalaska.uscg.mil	463-2453	463-2445
USCG (MSO Juneau)	Lt. Gary Koehler	Email	gkoehler@cgalaska.uscg.mil	463-2470	463-2445
Other	Name	Sent Via	Additional Info	Telephone	Fax
Responsible Party	John Hinchman	Mail	E-mail to Jay Kaino		
House/Dist. 5	Rep. Bill Thomas, Jr.	Fax	Session: Interim:	465-3732	465-2652
Senate/Dist. C	Sen. Albert Kookesh	Fax	Session: Interim:	465-3473	465-2827
City of Hoonah	Windy Skaflestad, Mayor	Fax		945-3663	945-3445
Hoonah Indian Association	Frank Wright, Jr., President	Fax		945-3545	945-3703
USDA Forest Service	John Baldwin, District Ranger	Email	jbaldwin0@fs.fed.us	945-3631 723-3192	
ADEC Solid Waste program	Ed Emswiler	Email			
SEAPRO	Dave Owings	Email	dave@seapro.org	225-7002	247-1117



Fishing gear and oil sheen from sinking of F/V Johnny A.