

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Spill Prevention and Response
Prevention and Emergency Response Program

SITUATION REPORT

INCIDENT NAME: Service Oil and Gas Truck Rollover **SITREP#:** 1

SPILL NUMBER: 06309915701 **LEDGER CODE:** 14163360

TIME/DATE OF SPILL: The exact time of the June 6, 2006 spill is unknown. The spill was reported to ADEC on June 6, 2006 at 4:50 PM by State Troopers

TIME/DATE OF SITUATION REPORT: 12:00 PM, on June 7, 2006

TIME/DATE OF THE NEXT REPORT: 12:00 PM, on June 8, 2006

TYPE/AMOUNT OF PRODUCT SPILLED: Unleaded gasoline, 850 – 900 gallons and a lesser but unknown volume of #1 heating oil as estimated by Service Oil and Gas Co.

LOCATION: Mile 173 Richardson Highway near Meiers Lake

CAUSE OF SPILL: Single vehicle accident. The cause of the accident is under investigation by State Troopers.

POTENTIAL RESPONSIBLE PARTY (PRP): Service Oil and Gas Co.

RESPONSE ACTION: The location of the accident was adjacent to Meiers Lake. As a result of the vehicle overturning, the gasoline and oil leaked from two of three of the truck's tank compartments into the roadbed. The fuel was found to be surfacing at the toe of the roadbed into a wet marshy area between the road and Meiers Lake. The damaged vehicle has been up-righted and removed from the road.

Upon arrival on the evening of June 6, response crews from Service Oil and Gas Co. deployed both hard boom and sorbent boom at the leading edge of the marsh drainage to prevent the fuel from migrating into the lake. Two recovery areas were established; at the toe of the road and in a natural collection area in the marsh. The contained fuel was recovered using sorbent pads and a wringer. Total estimated fuel volume collected from the marsh and toe of road is 124 gallons. The fuel surfacing from the roadbed slowed to a non-recoverable amount in the early morning hours of June 7, 2006. The booms are being maintained in place to protect the lake. An ADEC responder is on site to monitor and assist the response activities.

SOURCE CONTROL: The remaining fuel in the tank compartments was pumped out; the truck has been removed from the spill site.

RESOURCES AFFECTED: Marsh area by Meiers Lake, no sheen was found on Meiers Lake

FUTURE PLANS AND RECOMMENDATIONS: A traffic control plan is being drafted to facilitate on going response actions. This plan will be reviewed by highway safety. Plans are to establish an interception trench using an excavator, between the road and the lake. Water will be brought to the site in an attempt to flush fuel from the roadbed into the intercept trench for recovery. Disposal plans are being drafted for ADEC review and approval.

WEATHER: Sunny 50 to 55 ° F, wind speed 15mph.

UNIFIED COMMAND AND PERSONNEL:

Incident Commander Joe Stamm (Service Oil Co)
F.O.S.C..... Matt Carr (EPA)
S.O.S.C..... Ed Meggert (ADEC)
Field S.O.S.C..... Amanda Stark (ADEC)

FOR ADDITIONAL INFORMATION CONTACT: Ed Meggert 451-2124

Sitrep 1

AGENCY/STAKEHOLDER NOTIFICATION LIST

This sitrep has been distributed via email to the Governor's office, ADF&G, ADNR, SECC, USEPA, USDOJ, NMFS, USFWS, and USFS in addition to the following.

Agency/Organization	Name	Sent via	Additional Info	Telephone	FAX
Alaska State Troopers	Fairbanks	Fax		451-5100 or (800) 478-9300	451-5165
Alaska State Troopers	Delta Junction	Fax		895-4800	895-4026
ADNR	Leon Lynch/ Gary Schultz/ Larry Byrne	Fax		451-2724/ 451-2732	451-2751 or 659-2965
ADNR (Habitat)	Al Ott/Jack Winters	Fax		459-7285 or 459-7279	456-3091
ADF&G	Todd Nichols	Fax		459-7363	456-2259
Attorney General Office	Cam Leonard/ Mary Lundquist	Fax		451-2811/451-2914	451-2985
Legislature					
Legislator (Senate C)	Albert Kookesh (D)	Fax	Angoon	465-3473	465-2827
Legislator (Senate F)	Gene Therriault (R)	Fax	North Pole	465-4797 or (800) 860-4797	465-3884
Legislator (House 6)	Woodie Salmon (D)	Fax	Beaver	465-4527 or (800) 491-4527	465-2197
Legislator (House 12)	John Harris (R)	Fax	Valdez	465-4859	465-3799