



**ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION**  
**Division of Spill Prevention and Response**  
**Prevention and Emergency Response Program**

***SITUATION REPORT*** (*sitrep*)



**SIGNIFICANT CHANGES FROM PREVIOUS SITREPS ARE DENOTED IN RED**

## **Rampart Tanker Fuel Release**

**SITREP # 7 and Final**

**SPILL #:** 13309910101

**TIME/DATE OF DISTRIBUTION:** 1:00 p.m. July 8, 2014

**POTENTIAL RESPONSIBLE PARTY (PRP):** Rampart Village Council

**INCIDENT LOCATION:** On a road 300 yards west of the Rampart Airport, approximately 150 yards southeast of the Yukon River. (Lat/Long: 65.509017 N, 150.159167 W)

**TIME/DATE OF SPILL:** The spill occurred at 9:30 p.m. on April 11, 2013, and was reported to ADEC at 12:47 p.m. on April 12, 2013.

**TYPE/AMOUNT OF PRODUCT SPILLED:** Diesel fuel. ADEC responders determined the final volume spilled to be 2,750 gallons.

**CAUSE OF SPILL:** A bulldozer was pulling a tanker trailer down a snow-covered road to deliver fuel. The trailer went into the adjacent ditch and rolled, resulting in extensive damage to the aluminum tank and causing immediate release of the diesel fuel.

**SOURCE CONTROL:** The tank is not leaking. The remaining fuel was removed from the tank and moved off site.

**RESPONSE ACTION:** During the summer of 2013, Rampart Village Council hired a response contractor, Emerald Alaska Inc., to excavate the contaminated soil and to construct a bioremediation cell (bio cell) to treat the excavated soil. The construction of the bio cell allows the excavated soil to be treated locally and enhances biological degradation of the diesel fuel. The vertical and horizontal extent of contamination was not reached during the summer cleanup. Additional cleanup will be conducted at a later time. This case has been transferred to ADEC's Contaminated Sites Program for additional clean-up and site monitoring.

**RESOURCES AFFECTED:** Snow-covered forest floor has been affected by this incident. The land at the spill site drains towards the Yukon River. No wildlife impacts have been observed.

**FUTURE PLANS AND RECOMMENDATIONS:** ADEC's Contaminated Sites Program will continue to work with the Rampart Village Council to conduct additional cleanup and monitoring.

**WEATHER:** Today: sunny; high 57°F; east winds 5 mph. Tomorrow: partly Cloudy; high 65°F; west southwest winds 7 mph.

**UNIFIED COMMAND AND PERSONNEL:**

Incident Commander: Peggy Wright, Rampart Village Council  
SOSC: Tom DeRuyter, ADEC

**TIME/DATE OF THE NEXT REPORT DISTRIBUTION:** This is the final report.

**FOR ADDITIONAL INFORMATION CONTACT:** Ashley Adamczak, ADEC (907) 451-2124

This sitrep and additional photos are available at the following website:  
[http://dec.alaska.gov/spar/perp/response/sum\\_fy13/130411301/130411301\\_index.htm](http://dec.alaska.gov/spar/perp/response/sum_fy13/130411301/130411301_index.htm)

**AGENCY/STAKEHOLDER NOTIFICATION LIST:**

Please refer to the first sitrep, distributed April 14, for the agency/stakeholder notification list. The link to the first sitrep can be found in the **Additional Information** box above.