



ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Spill Prevention and Response
Prevention and Emergency Response Program
SITUATION REPORT



Tena Trucking Dalton Highway MP 58.6 Truck Rollover

SITREP #: 1

SPILL #: 15309908301

TIME/DATE OF DISTRIBUTION: 4:00 p.m. March 24, 2015

POTENTIAL RESPONSIBLE PARTY (PRP): Tena Trucking, LLC (Tena)

INCIDENT LOCATION: Dalton Highway milepost 58.6, approximately three miles north of the Dalton Highway Yukon River crossing.

TIME/DATE OF SPILL: The incident occurred at approximately 7:30 a.m. on March 24, 2015, and was reported to ADEC at 11:30 a.m. on the same day.

TYPE/AMOUNT OF PRODUCT SPILLED: The Tena tractor-trailer was transporting ultra-low sulfur diesel (ULSD) fuel. The punctured trailer compartment contained approximately 4,000 gallons of ULSD; exact volume released to be determined.

CAUSE OF SPILL: A northbound Tena tractor-trailer hauling fuel from Fairbanks to Deadhorse exited the west side of the roadway and rolled into the ditch. The front compartment of the trailer was punctured during the incident. The tractor, which separated from the trailer, remained upright and continued approximately 100 yards off the roadway. The driver is not believed to have been injured during the incident.

SOURCE CONTROL: None at this time.

RESPONSE ACTION: Tena has dispatched response personnel and is currently transferring fuel out of the damaged tanker.

One ADEC responder is on-site to monitor the response activities.

RESOURCES AT RISK OR AFFECTED: The closest body of water is approximately 1,500 feet from the spill site. The trailer landed inside a clear cut utility corridor which is expected to contain a fiber optic cable.

FUTURE PLANS AND RECOMMENDATIONS: Complete removing fuel from the tanker compartments to achieve source control, remove the truck and initiate removal of contaminated snow, debris and soil. Utility locates will be completed prior to commencing soil removal.

WEATHER: Tonight: A mix of clouds and sun; high 22°F; winds northeast at 5 to 10 mph. Tomorrow: Partly cloudy; high 26°F; winds north-northeast at 5 to 10 mph.

UNIFIED COMMAND AND PERSONNEL:


Incident Commander: To be determined

SOSC: Tom DeRuyter, ADEC

Field SOSC: John Ebel, ADEC

TIME/DATE OF THE NEXT REPORT DISTRIBUTION: 2:00 p.m. March 25, 2015

FOR ADDITIONAL INFORMATION CONTACT: Tom DeRuyter, SOSC, ADEC (907) 451-2145
http://dec.alaska.gov/spar/perp/response/sr_active.htm



Map of area along the Dalton Hwy, just north of the Yukon River; the red thumbtack shows incident location.

AGENCY/STAKEHOLDER NOTIFICATION LIST: This situation report was distributed to the agencies listed on the standard distribution list, which includes the governor's office, State Emergency Operations Center, U.S. Department of the Interior, National Marine Fisheries Service, U.S. Fish and Wildlife Service, and other state agencies. This situation report was also distributed to the following agencies and stakeholders:

AGENCY / STAKEHOLDER	NAME	SENT VIA	ADDITIONAL INFORMATION	TELEPHONE	FAX
Senate T	Donald Olson	Email	Senator.Donny.Olson@akleg.gov	465-3473 or (888) 288-3473	
Senate S	Lyman Hoffman	Email	Bethel 5/16 - 1/09 Juneau 1/10 - 5/15 Senator.Lyman.Hoffman@akleg.gov	543-3541 465-4453	543-3542 465-4523
House 39	Neal Foster	Fax	Nome 5/16-1/09 Juneau 1/10-5/15	465-3789 or (800) 478-3789	465-3242
House 38	David Guttenberg	Email	Representative.David.Guttenberg@akleg.gov		
Alaska State Troopers	Galena	Fax		656-1233	656-1530
Alaska State Troopers	Fairbanks	Fax		451-5100 or (800) 478-9300	451-5165
USCG Sector Anchorage	USCG Anchorage Office	Fax		428-4100	
US EPA	Bob Whittier	Fax/Email	Whittier.robert@epa.gov	271-3616	271-3424
ADF&G	Al Ott/Jack Winters	Email	al.ott@alaska.gov jack.winters@alaska.gov	459-7285 or 459-7279	
Attorney General Office	Steve Mulder	Email	Steve.mulder@alaska.gov	451-2811 or 269-5100	
Tanana Chiefs Conference	Jerry Isaac	Fax	President	452-8251 x 3433	459-3989