



ID	Location and Description	Response Strategy	Implementation	Response Resources	Staging Area	Site Access	Resources Protected (months)	Special Considerations
K-28-01 	Campbell Lagoon Nearshore waters in the general area of: Lat. 57° 51.5 N Lon. 153° 36.5 W	Free-oil Recovery Maximize free-oil recovery in the offshore & nearshore environment of Campbell Lagoon depending on spill location and trajectory.	Deploy free-oil recovery strike teams upwind and up current of Campbell Lagoon. Use aerial surveillance to locate incoming slicks.	Deploy multiple free-oil recovery strike teams as required to maximize interception of oil before it impacts sensitive areas.	Village Islands/Larsen Bay	Via marine waters Chart 16576-1	Same as K-28-02	Vessel master should have local knowledge. Use extreme caution, shoal waters with numerous reefs and rocks.
K-28-02 	Campbell Lagoon Lat. 57° 51.49 N Lon. 153° 38.12 W	Divert and Collect Divert oil to shore-side collection points determined by spill source and trajectory.	Deploy anchors and boom with inflatable raft or skiffs (class 6). Place protected-water boom at the proper angle to divert oil to collection site. Set up collection unit and tend throughout the tide.	Deployment Equipment 500 ft. protected-water boom 2 ea. small anchor systems 4 ea. anchor stakes 1 ea. shore-side collection unit Vessels 1 ea. Helicopter 1 ea. inflatable raft Personnel/Shift 2 ea. response techs Tending Vessels 1 ea. inflatable raft Personnel/Shift 2 ea. response techs	Vessel platform Local set-net site may provide logistic support and lodging.	Via marine waters Chart 16576-1	Fish- intertidal spawning-herring(April-May),salmon (May-Sept.) Birds-waterfowl concentration, eagle nesting Marine mammals-seals, otters Human Use-commercial fishing, subsistence Habitat- marsh, sheltered rocky shoreline	Take appropriate measures as outlined in Part 2 of this document to protect the beach at the collection site. A large bear population exists in the area; bear guards may be necessary. FOSC Historic Properties Specialist should INSPECT the site prior to operations. Title 41 permitting required from ADNR. Site surveyed: 7/19/05 KGRS Tactics Committee. Tested: not yet