

List of Devices with No Determination

As provided for in 18 AAC 50.077, ADEC approves wood-fired heating devices for sale within the Fairbanks Nonattainment area that are EPA certified and where the department has reviewed and accepted the underlying certification test results. ADEC has undertaken review of all devices on EPA’s certified list as of May 15, 2020 but moving forward will perform reviews of newly certified devices upon request. The following devices have been EPA approved and appear in the EPA database, however a request for review must be received by ADEC before a review of the certification report will commence.

Only after the review and any potential deficiencies identified have been corrected and approved will a device be placed on the Approved Device Lists.

To request that ADEC begin the review process refer to bottom of the page for instructions. For additional information regarding the ADEC review process please visit: <https://dec.alaska.gov/air/burnwise/manufacturers-vendors/>

This list will be updated at least monthly. If your device is not listed, and is EPA certified, please contact cory.mcdonald@alaska.gov.

Cordwood Devices’ Review		
Manufacturer	Models	AK List Status
509-1 Optimum	509 Fabrications, Inc.	Report Deficiencies not addressed
Arada Stoves Ltd	Farringdon 12	Report Deficiencies not addressed
Arada Stoves Ltd.	Farringdon 16	Report Deficiencies Not Addressed
Blaze King Industries, Inc.	King KE40	Report Deficiencies Not Addressed
Blaze King Industries, Inc.	Sirocco SC25, Ashford AF25, Boxer 24 (BX24)	Report Deficiencies Not Addressed
Enerco Group, Inc.	WS110	Reviewed – Information Required for approval
FPI / Fireplace Products International Limited	F1150, I1150	Report Deficiencies Not Addressed

FPI / Fireplace Products International Limited	F1500	Report Deficiencies Not Addressed
FPI / Regency Fireplace Products	F3500	Report Deficiencies Not Addressed
FPI / Regency Fireplace Products	I2450M, HI2450M	Report Deficiencies Not Addressed
FPI / Regency Fireplace Products	I2500	Report Deficiencies Not Addressed
Hearth and Home Technologies	QuadraFire 31M-ACC-C and QuadraFire Discovery-II-C	Report Deficiencies Not Addressed
Hearth and Home Technologies	Quadra Fire 43M-ACC-C, 43ST-ACC-C, Discovery-III-C	Report Deficiencies Not Addressed
Hearth and Home Technologies	Intrepid FlexBurn 2115-CAT	Review Request Recieved
Hearthstone Quality Home Heating Products Inc.	Bari, Bari Plus 8171 Hybrid	Report Deficiencies Not Addressed
Hussong Manufacturing Co.	Kozy Heat Z42, Kozy Heat Albany	Report Deficiencies Not Addressed
Innovative Hearth products	Montecito-B, Bainbridge (LVCFAR), WCT6920, WCT4920, WRT4920	Report Deficiencies Not Addressed
Innovative Hearth products	S210AGL, C210TGL, C210AGL, T2100GL, WSX2021WS-B	Report Deficiencies Not Addressed
Jotul	F45 V2	Report Deficiencies Not Addressed
Jotul North America	F55V2	Report Deficiencies Not Addressed
Jotul North America (Jotul U.S.A., Inc.)	F 500 V3	Report Deficiencies Not Addressed
Kuma Stove and Iron Works	K-250 Series, Ashwood LE, Wood Classic LE, Cambridge LE, Cascade LE	Report Deficiencies Not Addressed

MF Fire	Catalyst	Report Deficiencies Not Addressed
MF Fire	Nova	Report Deficiencies Not Addressed
Morso	6140 B, 6143 B, 6148 B, and 6170 B	Report Deficiencies Not Addressed
Morso Jernstoberi A/S	1410B, 1440B, and 1450B	Report Deficiencies Not Addressed
Morso Jernstoberi A/S	2B Standard 2020	Report Deficiencies Not Addressed
Morso Jernstoberi A/S	7110b	Report Deficiencies Not Addressed
New Buck Corporation	21 NC	Report Deficiencies Not Addressed
Pacific Energy Fireplaces	FP25LE, FP25AR LE	Report Deficiencies Not Addressed
Pacific Energy Fireplace Products Limited	Summit LE, Summit Classic LE, Alderlea T6 LE, and Summit Insert LE	Report Deficiencies Not Addressed
Pacific Energy Fireplace Products Limited	True North TN10	Report Deficiencies Not Addressed
Pacific Energy Fireplace Products Limited	Vista LE, Vista Classic LE, NEO 1.6 LE, Neostone 1.6 LE, Alderlea T4 LE (Freestanding), NEO 1.6 LE	Report Deficiencies Not Addressed
Rais A/S	Q-Tee II Steel, Q-Tee II Glass, and Q-Tee II C	Report Deficiencies Not Addressed
RSF / Industrial Chimney Company, Incorporated	Delta Fusion	Report Deficiencies Not Addressed
RSF / Industrial Chimney Company, Incorporated	Focus 320 SBR and Onyx SBR	Report Deficiencies Not Addressed
Spartherm	Spartherm M 700 Insert, Spartherm M 700 ZC, Spartherm M 700 Module	Report Deficiencies Not Addressed
Spartherm	Spartherm S 600 Insert, Spartherm S 600 ZC, Spartherm S 600 Module	Report Deficiencies Not Addressed
Stove Builder International Inc.	2.5 Series, Solution 2.5 ZC II, Stratford II, FP10 Lafayette II, FP12 Mundo II, Monaco II, HE250R, Destination 2.7, and Matrix 2700	Report Deficiencies Not Addressed

Alaska Department of Environmental Conservation
 Division of Air Quality

No Determination Device List
 Updated: 06-2024

Stove Builder International Inc.	3.3 Series Osburn 3300, Austral III, Myriad III, Legend III, Escape 1900, Black Stag II, Solution 3.3, Gateway 3300	Report Deficiencies Not Addressed
Stove Builders International	1.7 Series - Archway 1700, Gateway 1700, Columbia II, Savannah II, Deco II, HEI170, HES170, FW2800	Report Deficiencies Not Addressed
Stove Builders International	1.7 Series - Blackcomb II, Harmony 1.7, Solution 1.7, Osburn 1700, Inspire 1700, Escape 1500, Escape 1500-I, Solution 1.7-I, Destination 1.7-I, Osburn 1700-I, Matrix 1700-I, Inspire 1700-I	Report Deficiencies Not Addressed
STUV AMERICA Inc.	30 Compact, 30 Compact-H, 30 Compact-one	Report Deficiencies Not Addressed
Stuv America, Inc.	STUV 1658IN, STUV 1658CUBE, STUV 1658H, STUV 1658-Z	Report Deficiencies Not Addressed
Travis Industries	Answer	Report Deficiencies Not Addressed
Travis Industries	Answer NexGen Hybrid	Report Deficiencies Not Addressed
United State Stove Company	US1100E, VG1120, AW1120E, CH11, NM680, SW1.2, and AHWS1120	Report Deficiencies Not Addressed
United State Stove Company	US1269E	Report Deficiencies Not Addressed
United State Stove Company	US2000E, VG2020, AW2020E, CH20, NM890, SW2.0, and AHWS2020	Report Deficiencies Not Addressed
United State Stove Company	US2500E, AW2520E, VG2520, CH25, NM1190, SW2.5, and AHWS2520	Report Deficiencies Not Addressed
United States Stove Company	TR007E, US3200E VG3200, AW3200E	Report Deficiencies Not Addressed

United States Stove Company	US2941EB, VG4020, AW40, AW40E	Report Deficiencies Not Addressed
Hearth and Home Technologies	Vermont Castings Encore 2040-CAT-C	Review Request Received
Woodstock Soapstone	205 Fireview Catalytic	Report Deficiencies Not Addressed
Woodstock Soapstone Company	202 Palladian, 204 Keystone	Report Deficiencies Not Addressed
Woodstock Soapstone Company	209a Progress Hybrid	Report Deficiencies Not Addressed
Woodstock Soapstone Company, Inc.	210a Ideal Steel Hybrid	Report Deficiencies Not Addressed
Travis Industries, Inc	Endeavor NexGen-Hybrid	Report Deficiencies Not Addressed
Travis Industries, Inc	Large Flush Wood NexGen-Hybrid	Report Deficiencies Not Addressed
Kuma Stove and Iron Works	K-181 Series: Aspen LE-1, Tamarack LE-1, Aberdeen LE-1, and Alpine LE-1	Report Deficiencies Not Addressed
FPI / Regency Fireplace Products	F2500-1, I2500-1	Report Deficiencies Not Addressed
Hearthstone Quality Home Heating Products Inc.	Mansfield 8013	Review in Progress
Hearthstone Quality Home Heating Products Inc.	Green Mountain 60	Review in Progress
Pacific Energy Fireplace Products Limited	True North TN25-C	Report Deficiencies Not Addressed
Hearth and Home Technologies	Quadra-Fire Expedition II, Vermont Castings Montpelier II	Review in Progress
Blaze King Industries	Princess PE32	Review in Progress
Hearth and Home Technologies	Aspen C3	Review Request Received
Travis Industries	Endeavor NexGen-Hybrid	Review in Progress
Hearth and Home Technologies	Intrepid Flexburn 2115-Non-CAT	Review Request Received

Travis Industries	Large Flush Wood NexGen-Hybrid	Review Request Received
-------------------	--------------------------------	-------------------------

Pellet Devices' Review		
Manufacturer	Models	Status
American Energy Systems (AES)	3500P, 35001, and 3502	Report Deficiencies Not Addressed
American Energy Systems (AES)	Little Rascal	Report Deficiencies Not Addressed
American Energy Systems (AES)	Magnum Baby Countryside	Report Deficiencies Not Addressed
APR Industries Ltd.	Previa	Report Deficiencies Not Addressed
ARDISAM, Inc.	Serenity Castle	Report Deficiencies Not Addressed
Enerco Group, Inc.	PS130W	Report Deficiencies Not Addressed
Enerco Group, Inc.	PS20W	Report Deficiencies Not Addressed
Enerco Group, Inc.	PSBF66W	Report Deficiencies Not Addressed
England Stove Works Inc	25CAB80, 55-SHPCAB80, 55-TRPCAB80, 55-SHPCAB80S, 55- RPCAB80S	Report Deficiencies Not Addressed
England Stove Works Inc	25-CB120, 55-SHPCB120, 55-TRPCB120	Report Deficiencies Not Addressed
England Stove Works Inc	25-CBEP, 55-SHPCBEP, 55-TRPCBEP	Report Deficiencies Not Addressed
England's Stove Works, Inc.	25-CBPAH, 55-SHPCBPAH, and 55-TRPCBPAH	Report Deficiencies Not Addressed
England Stove Works Inc	25-PDVC, 25-PDVCH, 55-SHP10, 55-SHP10L, and 55-TRP10	Report Deficiencies Not Addressed
Even Temp, Inc.	Eclipse	Expired Report awaiting new report from retest

Alaska Department of Environmental Conservation
 Division of Air Quality

No Determination Device List
 Updated: 06-2024

Even Temp, Inc.	Hastings	Expired Report awaiting new report from retest
Even Temp, Inc.	Prescott EXP	Expired Report awaiting new report from retest
Gruppo Piazzetta S.P.A.	LIA, LISA	Report Deficiencies Not Addressed
Gruppo Piazzetta SPA	Sabrina 2.0, Sally 2.0, Solange 2.0, Sveva 2.0	Report Deficiencies Not Addressed
Hearth and Home Technologies	ECO Choice PS35-C, Quadra-Fire PS35-C	Report Deficiencies Not Addressed
Hearth and Home Technologies	PH50PS-B, PH50CABPS - B	Report Deficiencies Not Addressed
Hearth and Home Technologies	Harman Absolute 63	Report Deficiencies Not Addressed
Hearth and Home Technologies	Harman Accentra 52i-TC	Report Deficiencies Not Addressed
Hearth and Home Technologies	Harman Accentra-2	Report Deficiencies Not Addressed
Hearth and Home Technologies	Harman Allure 50	Report Deficiencies Not Addressed
Hearth and Home Technologies	Harman P43-C	Report Deficiencies Not Addressed
Hearth and Home Technologies	PelPro PPC90, PelPro TSC90, and Pleasant Hearth PHC90	Report Deficiencies Not Addressed
Hearth and Home Technologies	Quadra-fire Classic Bay 1200I- C	Report Deficiencies Not Addressed
Heat Tech Industries, LLC.	HTP 26 Bay, HTP26 Bay Pedestal/Insert	Report Deficiencies Not Addressed
Heat Tech Industries, LLC.	HTP 26 Standard	Report Deficiencies Not Addressed

Alaska Department of Environmental Conservation
 Division of Air Quality

No Determination Device List
 Updated: 06-2024

LMF Manufacturing Ltd dba America's Heat	America's Heat B-100	Report Deficiencies Not Addressed
Ravelli	Monica 2015, Francesca 2015, RV80 CERAMICA	Report Deficiencies Not Addressed
Ravelli	Roma	Report Deficiencies Not Addressed
Ravelli SRL	RV100 Classic	Report Deficiencies Not Addressed
Ravelli	RV120 Touch	Report Deficiencies Not Addressed
SBI	Osburn	Report Deficiencies Not Addressed
Sherwood Industries Ltd dba Enviro	Meridian-1, FPI, Cast Iron, GF55, GF155	Report Deficiencies Not Addressed
Sherwood Industries Ltd dba Hudson River Stove Works	EF2-1, Chatham-1, Davenport- 1, and Kinderhook-1	Report Deficiencies Not Addressed
Sierra Product, Inc.	EasyFire Pellet Stove, EF3801, EF5001, EF4001	Report Deficiencies Not Addressed
SMG Hearth & Home dba Comfortbilt	Comfortbilt HP22N, HP22, and HP22i Insert	Report Deficiencies Not Addressed
SMG Hearth & Home dba Comfortbilt	HP21	Report Deficiencies Not Addressed
SMG Hearth & Home dba Comfortbilt	HP54	Report Deficiencies Not Addressed

Alaska Department of Environmental Conservation
 Division of Air Quality

No Determination Device List
 Updated: 06-2024

SMG Hearth & Home dba Comfortbilt	HP55	Report Deficiencies Not Addressed
SMG Hearth & Home dba Comfortbilt	HP61	Review in Progress
Sun Mountain Stove Works Inc.	Whitney	Report Deficiencies Not Addressed
Thermorossi	Slimquadro 11	Report Deficiencies Not Addressed
Thermorossi	Slimquadro 9	Report Deficiencies Not Addressed
United States Stove Company	GW1949, AP77, SW1117	Report Deficiencies Not Addressed
United States Stove Company	KP5513, KP5513-P, KP5513-L, US5513, US5513-P, US5513-L, AP5613, AP5613-P, AP5613-L, VG5713, VG5713-P, VG5713-L, Little E (SP500), 5501S- XH	Report Deficiencies Not Addressed
United States Stove Company	5710, AP5710, VG5710, 5501S, AP5501S, VG5501S	Report Deficiencies Not Addressed
United States Stove Company	5780-E, AP5780-E, VG5780-E, SP5780-E, SP58-E	Report Deficiencies Not Addressed
United States Stove Company	5780, AP5780, VG5780, SP5780, and SP58	Report Deficiencies Not Addressed
Smokey's Stoves, LLC	Independence Stove GAP 2020 Non-Electric Pellet Stove	Review in Progress

Hydronic Pellet Devices' Review		
Manufacturer	Models	Status
Fröling Heizkessel und Behälterbau Ges.m.b.H	PE1 Pellet 20	Report Deficiencies Not Addressed
Fröling Heizkessel und Behälterbau Ges.m.b.H	PE1 Pellet 35	Report Deficiencies Not Addressed
Hargassner GmbH	ECO-HK 70 Multifuel	Report Deficiencies Not Addressed

Devices will not be reviewed without a formal request. In order to get a specific device reviewed follow the steps outlined below.

1. Send an email to cory.mcdonald@alaska.gov
2. Request that device be reviewed for inclusion in the Approved Device List
3. Identify device name.
4. Identify report number.
5. Device must be on EPA certified list.
6. Provide publicly available link of report for device.
7. The review process will take several weeks depending on the number of reviews currently being conducted.
8. Once review is completed, a copy of the summary report will be sent to Manufacturer for review. Report will be posted on the Manufacturer page after approximately 45 days unless errors or corrections are identified. Once complete, the summary report will be posted even if final determination is pending – minor or major, or disapproved. If final determination is pending, major or minor, the device will remain on this Pending Review with the Pending in the status column and will not be placed on the Approved List, until Pending items are addressed.
9. Until a final determination of Approved is made, the status column on the Pending Review List will be updated and used to indicate where in the review process the device's certification test is at.
 - a. Request Received
 - b. Reviewed-Information Required for approval
 - c. Report Deficiencies Not Addressed

Note: If final determination is Approved, the device will be removed completely from this list and placed on the Approved List.