

**ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION**  
**Division of Spill Prevention and Response**  
**Prevention and Emergency Response Program**

**SITUATION REPORT**

**INCIDENT NAME:** Service Oil and Gas Truck Rollover

**SITREP#:** 2

**SPILL NUMBER:** 06309915701

**LEDGER CODE:** 14163360

**TIME/DATE OF SPILL:** The exact time of the June 6, 2006 spill is unknown. The spill was reported to ADEC on June 6, 2006 at 4:50 PM by State Troopers. The accident occurred between 3:00 PM and 3:30 PM.

**TIME/DATE OF SITUATION REPORT:** 12:00 PM, on June 8, 2006

**TIME/DATE OF THE NEXT REPORT:** As the situation warrants.

**TYPE/AMOUNT OF PRODUCT SPILLED:** Service Oil & Gas estimates 850 – 900 gallons of unleaded gasoline. An unknown quantity of fuel spilled out of the truck's saddle tank. This is a corrected volume estimate from Sitrep 1 for this incident.

**LOCATION:** Mile 173 Richardson Highway near Meiers Lake

**CAUSE OF SPILL:** Single vehicle accident. The cause of the accident is under investigation by State Troopers.

**POTENTIAL RESPONSIBLE PARTY (PRP):** Service Oil & Gas Co. Service Oil & Gas is a subsidiary of Crowley Marine.

**RESPONSE ACTION:** The location of the accident was adjacent to Meiers Lake. As a result of the vehicle overturning, the 4500 gallon tank separated from the truck chassis. As the tank skidded down the road, the valve on the gasoline compartment was sheered off thus resulting in the spill. The valves on the other two compartments, carrying #1 and #2 heating fuel remained intact.

As of yesterday, no oil had been observed near the outer boom separating the marsh and Meier's Lake. A recovery trench was excavated yesterday at the base of the road. The trench is approximately 35' long and 6"-8" deep (down to frozen ground). The report this morning indicated that an additional 14 gallons had been recovered from the trench. Flushing operations will commence today. Water will be applied to the spill area in attempt to force more of the gasoline out of the bedrock and into the recovery trench.

ADEC staff will continue to coordinate with the response contractor to monitor the recovery activities.

**SOURCE CONTROL:** The remaining fuel in the tank compartments was pumped out; the truck has been removed from the spill site.

**RESOURCES AFFECTED:** Marsh area by Meiers Lake. No sheen has been observed on Meiers Lake

**FUTURE PLANS AND RECOMMENDATIONS:** A work plan is being drafted by the contractor that will outline future management options for this site. A disposal plan is also being drafted for ADEC review and approval.

**WEATHER:** Partly cloudy 55 to 60 ° F, south winds at 15mph.

**UNIFIED COMMAND AND PERSONNEL:**

Incident Commander ..... Joe Stamm (Crowley Marine)  
F.O.S.C..... Matt Carr (EPA)  
S.O.S.C..... Ed Meggert (ADEC)  
Field S.O.S.C.....

**FOR ADDITIONAL INFORMATION CONTACT:** Amanda Stark (907) 451-2175

Sitrep 2

**AGENCY/STAKEHOLDER NOTIFICATION LIST**

This sitrep has been distributed via email to the Governor's office, ADF&G, ADNR, SECC, USEPA, USDOJ, NMFS, USFWS, and USFS in addition to the following.

Agency/Organization	Name	Sent via	Additional Info	Telephone	FAX
Alaska State Troopers	Fairbanks	Fax		451-5100 or (800) 478-9300	451-5165
Alaska State Troopers	Delta Junction	Fax		895-4800	895-4026
ADNR	Leon Lynch/ Gary Schultz/ Larry Byrne	Fax		451-2724/ 451-2732	451-2751 or 659-2965
ADNR (Habitat)	Al Ott/Jack Winters	Fax		459-7285 or 459-7279	456-3091
ADF&G	Todd Nichols	Fax		459-7363	456-2259
Attorney General Office	Cam Leonard/ Mary Lundquist	Fax		451-2811/451-2914	451-2985
<b>Legislature</b>					
Legislator (Senate C)	Albert Kookesh (D)	Fax	Angoon	465-3473	465-2827
Legislator (Senate F)	Gene Therriault (R)	Fax	North Pole	465-4797 or (800) 860-4797	465-3884
Legislator (House 6)	Woodie Salmon (D)	Fax	Beaver	465-4527 or (800) 491-4527	465-2197
Legislator (House 12)	John Harris (R)	Fax	Valdez	465-4859	465-3799



Spill site photo with Meier's Lake in the background. ADEC photo.