

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Spill Prevention and Response
Prevention and Emergency Response Program

SITUATION REPORT

INCIDENT NAME: F/V *Midnite Sun* Grounding

SITREP #: 2

SPILL NUMBER: 11249904201

LEDGER CODE: 14308860

TIME/DATE OF SPILL: The F/V *Midnite Sun*, a 86-foot fishing vessel, grounded on the East side of Shelikof Straits in the vicinity of Tanaak Cape North of Malina Bay at 12:30 AM on February 11, 2011. The US Coast Guard (USCG) reported the grounding to ADEC at 12:40 AM on the same day.

TIME/DATE OF SITUATION REPORT: 3:30 PM on February 14, 2011

TIME/DATE OF THE NEXT REPORT: As situation warrants

TYPE/AMOUNT OF PRODUCT SPILLED: The operator of the vessel reported to the USCG that approximately 6,000 gallons of diesel fuel and 200 gallons of lube and hydraulic oil were on the vessel at the time of the grounding. An initial survey of the vessel was conducted on Saturday 02/12/2011 by the USCG personnel and the owner's agents. They determined that approximately 1500 gallons of diesel fuel was lost from one of the four fuel tanks on board the vessel. The status of the three remaining fuel tanks and the lube and hydraulic oil tanks has not been determined at this time. USCG reported that no fuel or sheen was observed around the vessel or on the adjoining shorelines during the initial site inspection.

LOCATION: East side of Shelikof Straits in the vicinity of Tanaak Cape, Malina Bay (58° 15' 82" N/153° 05' 83" W), approximately 36 nautical miles north northwest of the City of Kodiak.

CAUSE OF SPILL: The cause of the incident is under investigation by the USCG.

POTENTIAL RESPONSIBLE PARTY (PRP): Chesapeake, Inc. Anchorage, Alaska

RESPONSE ACTION: Upon notification of the incident, a USCG helicopter was launched from the Air Station Kodiak to the vessel grounding location. The USCG helicopter safely transported all five crew members on board the vessel back to Kodiak.

A site visit was conducted on Saturday 02/12/2011 and consisted of USCG personnel and salvage experts.

The PRP has contacted the vessel hull underwriters and are continuing the process of conducting a vessel inspection, developing a salvage plan to lighten the fuel and remove the vessel from the tide land.

SOURCE CONTROL: No source control implemented at the time of the grounding due to sea state and darkness. The vessel will be monitored daily, weather permitting, by the PRP until the remaining fuel on the vessel can be removed.

RESOURCES AFFECTED: Shorelines consist of gravel beaches with intermixed rocky outcrops. The area around Tannak Cape from Malina Bay to Paramanof Bay is designated as Northern sea otter habitat. Steller sea lions are present on haulouts and in the areas of Cape Paramanof and Cape Malina. These animals are listed as endangered species in this area under the Endangered Species Act and should command a high priority for protection in the event of a spill. The vessel is aground within the designated critical habitat for the Steller sea lion. Waterfowl choosing to overwinter in the area is also increasing each year. Therefore, some overwintering waterfowl may be present. Waterfowl present may include mergansers, harlequin ducks, and similar species. No historic or cultural resources are affected at this time.

FUTURE PLANS AND RECOMMENDATIONS:

The PRP's salvage contractor will develop a salvage plan for review by USCG and ADEC. Due to high winds and rough sea state, no fuel removal or salvage operation is anticipated to commence until the weather conditions improve.

WEATHER: Gale warning today Northwest winds to 40 knots, with gust to 50 knots, seas 7 feet, heavy freezing spray. Tonight - Northwest winds 30 knots, seas 6 feet, heavy freezing spray. Tuesday - Northwest winds 25 knots, seas 5 feet, snow showers, heavy freezing spray.

UNIFIED COMMAND AND PERSONNEL:

Incident Commander: Clint Parks, Chesapeake, Inc.
F.O.S.C.: CAPT Jason Fosdick, USCG
S.O.S.C.: John Brown, ADEC

FOR ADDITIONAL INFORMATION CONTACT: John Brown, ADEC, (907) 269-7688

Photographs and other spill information are available for viewing at:
<http://www.state.ak.us/dec/spar/perp/index.htm>

AGENCY/STAKEHOLDER NOTIFICATION LIST

This sitrep has been distributed to the following agencies and stakeholders. This situation report was also distributed to the various agency staff listed on the standard distribution list. The receiving agencies listed in the standard distribution list includes: Governor's office, Senator Begich's office, ADF&G, ADNR, SECC, EPA, DOI, NMFS, and USFWS.

AGENCY/STAKEHOLDER	NAME	Sent Via		Telephone	Facsimile
ADEC	Field Office, Kodiak EH	Email		486-3350	486-5032
USCG-MSO/KOD	USCG -Office	Fax		486-5918	487-5585
USCG-MSO/ANC	USCG- Office	Fax		271-6700	271-6751
US EPA	Bob Whittier	Fax		271-3616	271-3424
PWS RCAC	Mark Swanson	Fax		835-5957	835-5926
CIRCAC	Mike Munger	Fax/Email	munger@circac.org	283-7222	283-6102
City of Kodiak	City Manager	Fax		486-8640	486-8600
Kodiak Is. Borough	Borough Office	Fax		486-9360	486-9396
Ouzinkie Tribal Council	Council Office	Fax		680-2259	680-2310
Native Village of Port Lions	Office	Fax		454-2234	454-2434
Native Village of Karluk	Office	Fax		241-2218	241-2208
Afognak Native Corporation	Office	Fax		486-6014	486-2514
Koniag Inc.	Office	Fax		486-2530	486-3325
City of Larsen Bay	Office	Fax		847-2211	847-2239
			Session/Interim		
House 36/Kodiak	Alan Austerman	Fax	Kodiak 5/16 - 1/09 Juneau 1/10 - 5/15	486-8872 465-2487	486-5264 465-4956
Senate R/Kodiak	Gary Stevens	Fax	Juneau 5/16 - 1/09 Juneau 1/10 - 5/15	486-4925 465-4925	465-3517 465-3517
Afognak Native Corporation	Howard Valley		howard@afognak.com	486-6014	



Damage to vessel hull, photo provided by Alaska Marine Surveyors, Inc.