STATE OF ALASKA

DEPT. OF ENVIRONMENTAL CONSERVATION

DIVISION OF SPILL PREVENTION AND RESPONSE CONTAMINATED SITES PROGRAM

SARAH PALIN, GOVERNOR

555 Cordova Street Anchorage, AK 99501 PHONE: (907) 269-3057 FAX: (907) 269-7649 www.dec.state.ak.us

File: #300.38.260

July 28, 2008

Michael Nelson ConocoPhillips P.O. Box 100360 Anchorage, AK. 99510-0360

Re:

ConocoPhillips West Sak 24

Record of Decision

Dear Mr. Nelson:

The Alaska Department of Environmental Conservation, Contaminated Sites Program (ADEC) reviewed the environmental records associated with West Sak 24. This site had been contaminated by the release of a hazardous substance; however, based on the information provided to date, ADEC has determined that no further remedial action is required, and that West Sak 24 can be closed subject to the conditions outlined in this document. The hazardous substance contamination has been adequately addressed and does not pose an unacceptable risk to human health or the environment. This site is included on the Existing (Contaminated) Sites Charter for the Development of the Alaska North Slope (Paragraph II.A.3; Exhibit D.2).

This decision is based on the administrative record for this site which is located in the offices of the ADEC in Anchorage, Alaska. This letter summarizes the decision process used to determine the environmental status of this site and provides a summary of the regulatory issues considered in the ADEC determination.

Introduction

Site Name and Location ConocoPhillips West Sak 24 Milne Point Access Road Prudhoe Bay, AK

Name and Mailing Address of Contact Party: Michael Nelson ConocoPhillips P.O. Box 100360 Anchorage, AK. 99510-0360

<u>Database Record Key and CS file number:</u> ADEC Reckey # 1999360121301

G:\SPAR\SPAR-CS\38 Case Files (Contaminated Sites)\300 Deadhorse - Prudhoe - Kuparuk\300.38.260 ConocoPhillips West Sak 24\ConocoPhillips West sak 24 ROD.doc

CS file #300.38.260

Regulatory authority under which the site is being cleaned up:

18 AAC 75 and 18 AAC 70

Background

West Sak 24 is an exploration drilling site located one mile north of the Spine road on the Milne Point Access road. One well was drilled at the pad in 1982 that was plugged and abandoned in 1995. Diesel contamination was found near the former well on the gravel pad during investigations conducted in 1999 and 2000.

Site Characterization

Site investigations were conducted in 1999 and 2000. Boreholes were drilled at various locations across the pad. Soil samples collected from boreholes indicated petroleum contamination was present near the former well head. DRO concentration in this area ranged from 750 mg/kg to 2,680 mg/kg

Contaminants of Concern

Diesel Range Organics

Cleanup Levels

The cleanup levels for petroleum hydrocarbon-contaminated soil on manmade gravel pads and roads in the Arctic Zone are established in 18 AAC 75.341 Method One, Table A2 and 18 AAC 75.341 Method Two Tables B1 and B2.

A number of factors are considered by ADEC when evaluating site specific cleanup levels in the Arctic Zone including:

- human health (ingestion/inhalation);
- ecological impacts (contamination impacting ecological species other than humans);
- water (ground and surface) quality;
- presence of free phase product; and
- any other factors that might cause a deleterious impact to the environment.

In the Arctic Zone, the migration to surface water pathway is evaluated as the primary migration pathway since the migration to groundwater pathway is not considered applicable due to the presence of continuous permafrost.

The 18 AAC 75.341 Method Two Table B2 regulations also limit soil hydrocarbon concentrations to a "maximum allowable concentration". This concentration was established based on a specific soil type in which hydrocarbon product may become mobile as a separate phase and migrate in the soil. If a petroleum hydrocarbon exceeds a soil saturation limit, there may be an increased risk of migration off the gravel pad to surface water or tundra that has to be evaluated when making environmental decisions. Therefore, the soil type must be evaluated when establishing cleanup levels in the Arctic Zone to ensure the petroleum hydrocarbon does not exceed the residual saturation levels and pose a risk by migrating.

ADEC has evaluated the current site specific information regarding North Slope soil types and considers a coarse gravel soil type to be representative of those gravel pads rather than a fine sandy silt soil that was considered when establishing the Table B2 Arctic Zone levels. The

diesel range saturation point in a coarse gravel material is 2200 mg/kg; the gasoline range saturation point is 950 mg/kg with residual range being 4800 mg/kg.

NOTE: Even though the migration to groundwater pathway is not complete in the Arctic Zone, the soil cleanup levels established for the migration to groundwater pathway in the Over 40 inch Zone are considered to be the most stringent cleanup levels, and protective of human health and the environment. If these cleanup levels are achieved at an Arctic Zone site, it will allow for unrestricted closure. In addition, the 18 AAC 75.341 Method One Table A2 cleanup levels may also be considered when making a final closure determination. Either Method One or Method Two migration to groundwater cleanup levels are considered protective to allow full site closure. The guidance document, "Policy for Establishing Cleanup Levels for Sites in the Arctic Zone in Accordance With 18 AAC 75, Article 3," provides additional information for management of residual contamination in the Arctic Zone.

Pathway Evaluation

The human health (HH) exposure pathways that were evaluated for this decision document included: inhalation of outdoor air; ingestion of soil; dermal contact with soil; and ingestion of groundwater. The inhalation and ingestion pathways may be complete but contaminant concentrations do not exceed 18 AAC 75.341 Table B2, Method Two risk based cleanup levels for either ingestion or inhalation. Therefore, the HH exposure risk is considered acceptable. The dermal contact may be complete, but contaminated soil is located below the surface of the pad and is not available to receptors.

In the Arctic Zone, the migration to surface water pathway is evaluated as a possible risk to human health (drinking water source) and/or for compliance with Alaska Water Quality standards (18 AAC 70). Any surface water adjacent to this pad is not a drinking water source; therefore, the human exposure pathway is not considered complete.

In addition, the migration to surface water is evaluated as a possible exposure pathway for ecological receptors because of the tundra wetland ecosystem that exists throughout the Arctic region. The migration to surface water pathway may be complete but sampling indicates surface water has not been impacted.

The exposure pathway analysis above was supported by the most recent ADEC Exposure Tracking Model (ETM) ranking. The ETM results showed all pathways to be one of the following: De Minimis Exposure, Exposure Controlled, or Pathway Incomplete.

ADEC Decision

There is contamination remaining above established cleanup levels at ConocoPhillips West Sak 24, but ADEC has determined there is no unacceptable risk to human health or the environment, and this site will be conditionally closed.

This decision is subject to the following conditions:

1. A Notice of Residual Contamination will be recorded on the ADEC database to document residual contamination remaining on site above the most stringent ADEC cleanup levels. This will serve as notification to future owners/operators of the property of the environmental status of the site and any conditions that apply to future management of contamination.

- 2. When the pad is decommissioned, contaminated gravel must be removed and disposed of in accordance with 18 AAC 75 and an ADEC-approved work plan.
- 3. Any proposal to transport soil off site requires ADEC approval in accordance with 18 AAC 75.370 (b).
- 4. Soil containing residual contamination may not be placed in surface water or other environmentally sensitive areas.

This determination is in accordance with 18 AAC 75.380 (d) and does not preclude ADEC from requiring additional assessment and/or cleanup action if future information indicates that this site may pose an unacceptable risk to human health or the environment.

Site closure (without conditions) can be achieved when soil sampling confirms that all soil meets the most stringent ADEC cleanup levels.

Appeal

Any person who disagrees with this decision may request an adjudicatory hearing in accordance with 18 AAC 15.195-18 AAC 15.340 or an informal review by the Division Director in accordance with 18 AAC 15.185. Informal review requests must be delivered to the Division Director, 410 Willoughby Avenue, Suite 303, Juneau, Alaska 99801, within 15 days after receiving the department's decision reviewable under this section. Adjudicatory hearing requests must be delivered to the Commissioner of the Department of Environmental Conservation, 410 Willoughby Avenue, Suite 303, Juneau, Alaska 99801, within 30 days after the date of issuance of this letter, or within 30 days after the department issues a final decision under 18 AAC 15.185. If a hearing is not requested within 30 days, the right to appeal is waived.

If you have questions about this closure decision, please contact ADEC Project Manager William O'Connell at (907) 269-3057.

Sincerely,

Linda Nuechterlein Environmental Manager

Cc Gary Schultz, ADNR Fairbanks
Sarah Kenshalo, Weston Solutions
Lori Aldrich, ADEC Solid Waste Program