



P.O. Box 55878
North Pole, AK 99705
(907) 488-4999 • FAX (907) 488-4823

CERTIFICATION OF THERMAL TREATMENT

This undersigned hereby certifies that the below described material has been thoroughly tested and remediated to less than 50 PPM AK101 and 100 PPM AK02, 2000 PPM AK103, and 0.02 PPM Benzene in accordance with Alaska Department of Environmental Conservation Level A Clean-Up Standards and under our ADEC Air Quality Permit No. AQ0325TVR01.

Client	Project
Bea Mountain Investments c/o H Von Lawrence 751 Seventh Ave Fairbanks, Alaska 99701	Thermal remediation, post testing and final disposal of 49.89 tons of POL contaminated soil from 184 Palace Circle

The test results demonstrating successful remediation are attached and described as follows:

State	Lab Reference	Contract	AK101	AK102	AK103	Benzene
115	1111001-001	11-062N-1-PC	ND	ND	ND	ND

Testing Lab: Test America, 2000 W International Airport Road, Ste. A-10, Anchorage, AK 99502-1119

The undersigned further certifies that they are familiar with the information contained in this document and to the best of their knowledge and belief the information is true, complete and accurate.

Signature:

Mark W. Sanford
Mark W. Sanford, Director

Date:

11-24-2011