


AREAS NOT ADDRESSED BY ARCO BUT MAY REQUIRE REMOVAL OF PCB

AREA THAT ARCO BELIEVES WILL REQUIRE ADDITIONAL EXCAVATION



- E + E SAMPLE LOCATION: () ANALYTICAL RESULTS FOR PCBs REPORTED IN ppm.
- OIL SAMPLE TEST HOLES ANALYSE BASE OF CPF "10" NOT MENTIONED

* A TOTAL OF 394 SOIL, OIL, AND WIRE SAMPLES WERE COLLECTED FROM 7-9-94 THROUGH 6-8-94. THE SAMPLE LOCATIONS AND RESULTS ABOVE INDICATE THE CUSTOMER WOULD BE RESPONSIBLE FOR BACKFILL AND LINER WERE INSTALLED.

Ecology and Environment, Inc.	
SCALE: 1/4" = 1'-0"	APPROVED BY: <i>[Signature]</i>
DATE: 10-20-94	DRAWN BY: <i>[Signature]</i>
CPF - PIPELINE SOIL SAMPLES	
E + E SCREENS FROM 7-9-94 - 10-19-94	DRAWING NUMBER: 01

Bill Heber