

RECONNAISSANCE CLOSURE REPORT

L

SITE/FACILITY NAME: Gravel Plant

ADEC SITE NUMBER:

None

SITE LOCATION:

Physical Address

Name

Address Ridgeway Rd. 200 yds N.

City, Zip at Kenai spur Rd.

Phone#

Mailing address

Name

Address

City, Zip

LEGAL DESCRIPTION: TSN, R10W SEC 20 & 29 S.M.

DIRECTION TO SITE: Pit behind Alaska Road Builders - another pit across Ridge Way Rd. Both pits have possible hot mix activities there.

PROBLEM INVESTIGATED: (liquid) Waste from hot mix plant.

SITE VISIT:

DATE: 2/22/01

ADEC INVESTIGATOR: Rob Messingill / Rick Conover

FINDINGS:

Two large ^{gravel} pits both ~~East & West~~ ^{North & South} of Ridgeway road just 200 yds from the spur hwy. were found.

Debris on the ~~west~~ ^{North} pit was present. Snow cover prevented observation of any ground staining. This site should be revisited after snow melt.

CONTAMINATED SITES FOLLOWUP REPORT

SITE DESCRIPTION/FACILITY NAME:

Ridgeway Rd Gravel Pit

DATE: 5/22/91

ADEC INVESTIGATOR: Harley Perkins

ADEC SITE NUMBER: 91-2-3-1-143-2

SITE LOCATION:

Physical Address: Gravel Pit off Ridgeway Rd.

RESPONSIBLE PARTY: Ronald Davis / AK. Roadbuilders

ENVIRONMENTAL SETTING:

Geology and soils: Next to Gravel pit so probably sandy - Gravel

Surface and groundwater:

Land Use: Gravel Pit

Water supply:

PROBLEM STATEMENT

Found numerous 55 gal. drums with staining in 4 around drum
Found some type of unknown muds dump to ground. 3 large piles. Found asphalt-
like substances dumped to ground, a good 40 to 50 ft long 10 ft wide. Found dead
bird in substance. Found about 15 batteries improperly stored on ground.

PREVIOUS & CURRENT CONTAMINATION ASSESSMENT

SITE ASSESSMENT:

N/A



RESULTS OF FINDINGS:

N/A

REMEDIAL ACTION:

N/A

CONCLUSIONS:

No.V. issued 5/4/91