


At 5/8/87



* Check well integrity on these pads

ecology and environment

FIGURE 6-3 THE SEQUENCE OF EXCAVATION and ON-SITE TRANSPORTATION ROUTES