Date: 7-23-22			
Time: 0954			
Recorder:OIC Suttle			
Weather: Partly Cloudy	У		
Wind Direction: S - SW	Wind Speed (mph): 8	Temperature (°F):	57
Description of Sheens  Not Visible - Barely Vi  Additional notes:		- Obvious and requires	s additional action

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

**Obvious:** clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken





Date: 7-24-22				
Time: 1020				
Recorder:S/C	) Cole			
Weather: Clo	udy			
Wind Direction: S	Wind S	peed (mph): 12	Temperature (°F):	58
Description of  Not Visible  Additional no	f Sheen: Not Vis  Barely Visible - otes:		Obvious and requires	additional action

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

**Obvious:** clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken





## Daily Check – Kenai Beach Sheen

Date: 1/0	16/22	
Time: 2:40	Spm.	
Recorder: 1	1. La Viguer	
Weather: Su	unny	
Wind Direction:	Wind Speed (mph):	Temperature (°F):
NE	20 mph	56
Description of S	heen:	
Not Visible - Ba	rely Visible - Obvious	- Obvious and requires additional action
Additional note	es:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken.





## Daily Check – Kenai Beach Sheen

Date: 7	121/22	<b>-</b> :
Time: 3	5:31 pm	<del>_</del>
Recorder:	M. Lewiguer	
Weather:	M. Lewiguer Sunny	_
Wind Direction:	Wind Speed (mph):	Temperature (°F):
SE	11	66
Description of		
Not Visible -	Barely Visible - Obvious	- Obvious and requires additional action
Additional no	otes:	
i <del></del>		

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken.





Date: 7-30-22			
Time: 1017			
Recorder:S/O Scott			
Weather: Cloudy			
Wind Direction: <b>SW</b>	Wind Speed (mph): 7	Temperature (°F):	57
Description of Sheen:	Not Visible		
Not Visible - Barely Vi	sible - Obvious	- Obvious and requires	additional action
Additional notes:			

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

**Obvious:** clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken



Date: 7-31-22			
Time:0921			
Recorder: OIC Suttle			
Weather: Cloudy			
Wind Direction: <b>NE</b>	Wind Speed (mph): 12	Temperature (°F):	57
Description of Sheen:  Not Visible - Barely Vis		Obvious and requires	additional action
• Barery VIS	Obvious	Obvious and requires	additional action
Additional notes:			

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

**Obvious:** clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken

