Date: 5-1-23	
Time: 1734	_
Recorder: B. CASON	
Weather: CLOUPY	
Wind Direction: SW Wind Speed (mph):	← Temperature (°F): ← / / / / / / / / / / / / / / / / / /
	, ,
December of Clares	
Description of Sheen:	
Not Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 5-2-23	
Time: /800	
Recorder: B. CASO N	<u>.</u>
Weather: SHOWERS	_
Wind Direction: Wind Speed (mph):	8 Temperature (°F):38
Description of Sheen:	
Not Visible Barely Visible - Obvious	- Obvious and requires additional action
Additional notes:	
,	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 5-3-23	
Time: 18:00	_
Recorder: B. CASON	-
Weather: CLOVOY	
Wind Direction: S W Wind Speed (mph):	6 Temperature (°F): 40
*	
Description of Sheen:	
Not Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date:	5-4-23		
Time:	18:41		
	B. CASON		
Weather:	CLOUDY		
Wind Direction	: Wind Speed (mph): 1	Temperature (°F):	45
_			
Description	of Sheen:		
Not Visible -	Barely Visible - Obvious -	Obvious and requires a	dditional action
Additional	notes:		

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Additional r	notes:		
Not Visible -	Barely Visible - Obvio	us - Obvious an	d requires additional action
Description (of Sheen: <u>Not visible</u>		
Wind Direction:	S Wind Speed (mph): 5	Temperature (°	F): 35°F
Weather:	Cloudy		
Recorder:	J. Godfrey		
Time:	0958		
Date:	5-6-23		

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



5-7-23			
1100			
R. Scott			
Partly Cloudy			
N Wind Speed (mph):	5	Геmperature (°F):	40°F
of Sheen: Not Visible			
Barely Visible - Obv	vious -	Obvious and red	quires additional action
otes:			
	R. Scott Partly Cloudy Wind Speed (mph): of Sheen: Not Visible	R. Scott Partly Cloudy Wind Speed (mph): 5 of Sheen: Not Visible Barely Visible - Obvious -	R. Scott Partly Cloudy Wind Speed (mph): 5 Temperature (°F): of Sheen: Not Visible Barely Visible - Obvious - Obvious and recommendations

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: MAY 8, 2023	
Time: 9:43 7m	
Recorder: SP	
Weather: CLEAR	
Wind Direction: WA Wind Speed (mph): NA	Temperature (°F): 45°
Description of Sheen: NO SHEEN	*
Not Visible - Barely Visible - Obvious -	Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 5-10-23	_
Time: 17:48	_
Recorder: B. CasoN	
Weather: CLUVDY	
Wind Direction: Wind Speed (mph):	Z STemperature (°F): 47
Description of Sheen:	
Not Visible - Barely Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 5-11-13	_
Time: 20:05	
Recorder: B. Cason	_
Weather: CLOUPY	_
Wind Direction: Wind Speed (mph):	7 Temperature (°F): 5Z
Description of Sheen:	
Not Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 5-13-2023 Time: 1300 Officer Scott Recorder: Weather: Sunny Wind Direction: variable Wind Speed (mph): less than 5 kts Temperature (°F): 49 °F Description of Sheen: **Not Visible** Obvious and requires additional action **Barely Visible** Obvious Additional notes: No sheen, no odor, no problem

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.

