Date: 6-12-23	
Time: 8:02	_
Recorder: B. CASON	
Weather: CWVDY	_
Wind Direction: S Wind Speed (mph):	1 Temperature (°F): 46
Description of Sheen:	
Not Visible - Barely Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 6-13-23	
Time: 12:07	
Recorder: B.CASON	
Weather: CLOVDY / WIND	
Wind Direction: 5 Wind Spec	ed (mph): 22 Temperature (°F): 48
575	
Description of Change	
Description of Sheen:	
Not Visible - Barely Visible -	Obvious - Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Additional r	notes:					
Not Visible -	Barely Vis	sible -	Obvious	-	Obvious and requires	additional action
Description o	of Sheen:	Not Visibl	e			
Wind Direction:	NE	Wind Spe	eed (mph):	9	Temperature (°F):	54
Mind Divo eti - :-	•	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	( / / / / / / / / / / / / / / /	_	Tamananatura (°C)	Г 1
Weather:	Cloudy					
Recorder:	R. Scott					
Time:	1416					
Date:	6-17-23					

**Not Visible:** no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

**Obvious:** clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken.



Additional r	notes:					
Not Visible -	Barely Vis	sible -	Obvious	-	Obvious and requires	additional action
AL-LAC-THI-	David 30	-9.1.	Ola ta		Ob to see how t	
Description (	of Sheen:	Not Visible	e			
Wind Direction:	NE	Wind Spe	ed (mph):	5	Temperature (°F):	56
Weather:	Cloudy			_		
Recorder:	R. Scott					
Time:	0822					
Date:	6-18-23			_		

**Not Visible:** no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

**Obvious:** clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken.



	1191	23				Ÿ	
Date:	1 1	<del></del>		_			
Time:	6:3	1					
Recorder:	R.(	Ason		·			
Weather:	RAI	N					
Wind Direction:	N	Wind Spe	ed (mph):	7	Temperature (	°F): 5	+
Description o	of Sheen:						
Not Visible -	Barely Vis	ible -	Obvious	- OI	ovious and requ	ires additio	nal action
Additional n	otes:						

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 6/20/23 Time: 12:53	·
Time: 12:53	<del></del>
Recorder: B. Casow	
Weather: RAIN	<del></del>
Wind Direction: Wind Speed (mph):	Fremperature (°F): 53
Description of Sheen:  Not Visible - Barely Visible - Obvious  Additional notes:	- Obvious and requires additional action

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 6	21/23		<del>f</del>
Time:	21/23		
Recorder:	3. Cason	_	
Weather:	CLOUDY	_	
Wind Direction:		Temperature (°F):	50
Description of	f Sheen:		
Not Visible	Barely Visible - Obvious	- Obvious and requires	additional action
Additional no	otes:		

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



1.	11	0 2			¥
Date: 🗸	27	V3			
Time:	6:2	\			
Recorder:	B C	ason			
Weather:	CLOU	400	·		
Wind Direction:	W	Wind Speed (mp	h): 5	Temperature (°F	): 5
Description (	of Sheen:				
Vot Visible -	Barely Vis	sible - Obvio	ıs - O	bvious and require	es additional action
Additional n	otes:				

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 2S square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



# DailyCheck—Kenai Beach Sheen

Date: 6-24-23			
Time: 1327			
Recorder: Alex Ross			
Weather: Overcast			
Wind Direction: <b>WNW</b>	Wind Speed (mph): 4.7	Temperature (°F):	52
Description of Sheen:  Not Visible - Barely Visible Additional notes:		Obvious and requires	additional action

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

**Obvious:** clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken

File: 0600-004-033



# DailyCheck—Kenai Beach Sheen

Date: 6-25-23			
Time: 1357			
Recorder: C. Herrick			
Weather: Overcast			
Wind Direction: SW	Wind Speed (mph): 13	Temperature (°F):	52
Description of Sheen:  Not Visible - Barely Vis		- Obvious and requires	s additional action
Additional notes:	C	C	
Additional notes:			

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

**Obvious:** clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken

File: 0600-004-033

