Thane Road
Bunker Oil Tanks
Photo Galley, 2005-06

North Tank
Summer 2005



Steep Access Road – View North
Summer 2005

North Tank Runoff
Summer 2005

North Tank Site Preparation – View South with Cruise Ship in Background
Summer 2005

North Tank – Oily Liquid and Debris Mixture
Fall 2005

North Tank – Incinerators and Holding Tanks in Background
Fall 2005

Temporary Holding Tanks
with Oily Waste

Open-Topped Holding Tank
Fall 2006

Sorbent Booms to Prevent Runoff
Fall 2006

Perimeter Ditch to Divert Water Away From Tanks Fall 2006

North Tank – View Southeast
Fall 2006

Thane Bunker Tank, Loading the tank with diatomaceous earth. 17Oct2007. ADEC Photo BMattson
Active remediation work, October 17, 2007
Diatomaceous Earth mixing with the oil
Tank Bottom
Dewatering Sump

Active remediation work,
October 19, 2007