


Locational information is approximate and does not confirm or deny the presence of hazardous material. The data is to be used for purposes of reference only. This map was developed using the best available information and has undergone several iterations of quality control. Therefore the map is an accurate depiction of the data used to create it, but may still differ from the actual site conditions. Analytical data originated from the Alaska Department of Environmental Conservation (ADEC) while other base data was acquired from the Alaska Department of Natural Resources (ADNR). This locational information is based on the North American Datum of 1983 and uses a Universal Transverse Mercator projected coordinate system, Zone 6. The base image is a QuickBird Satellite taken in May, 2002 in a true color projection. Spatial resolution is approximately 0.6 meters and has a tested average accuracy of 1.5 meters.



Bentley Mall East Satellite Building
Figure 2



January, 2004

