Alaska Department of Environmental Conservation
ADOT&PF Peger Road Facility
Fairbanks, Alaska

ESTIMATED CONTAMINANT PLUME BOUNDARIES

June 2009 31-1-11438-006

SHANNON & WILSON, INC. GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS

FIGURE 6