



**Legend:**

- |                    |                                  |   |
|--------------------|----------------------------------|---|
| BTEX Results       | ● Recovery Well                  | — Benzene Isopleth in µg/L<br>(Dashed where inferred) |
| ● Monitoring Well  | ■ Vertical Profile Transect Well | ▭ Fhra Property Boundary                              |
| ● Observation Well | ▲ Surface Water                  |   |

**Notes:**

Results are displayed in µg/L  
 BTEX Benzene, toluene, ethylbenzene and total xylenes  
 < Not detected; detection limit listed  
 - - Not sampled due to cold weather constraints  
 † Total Xylenes calculated by SWI  
 ‡ BTEX analyzed by USEPA Method 624 (equivalent to SW8260B)  
 \* Result is considered estimated (no direction of bias) due to QC failures (flagged by SWI)

Image date June 9, 2007

FLINT HILLS RESOURCES ALASKA, LLC  
 NORTH POLE REFINERY, NORTH POLE, ALASKA  
**FOURTH QUARTER 2012  
 GROUNDWATER MONITORING REPORT**

**ANALYTICAL RESULTS FOR BTEX  
 AT WATER TABLE**

	FIGURE <b>4-9</b>
---	----------------------