



Rodney P. Kinney Associates, Inc.
Sustaining Ecosystems & Resources

CROOKED CREEK TRADITIONAL COUNCIL
P.O. BOX 69
CROOKED CREEK, ALASKA 99575

CROOKED CREEK COMMUNITY MAP

DESIGNED BY	NSC
DRAWN BY	SPK/CS
CHECKED BY	NSC
DATE	JANUARY 20, 2011
SCALE	1"=800'

FIGURE 1

Photo locations



GRAPHIC SCALE



Rodney P. Kinney Associates, Inc.
Sustaining Ecosystems & Resources

CROOKED CREEK TRADITIONAL COUNCIL
P.O. BOX 69
CROOKED CREEK, ALASKA 99575

CROOKED CREEK COMMUNITY MAP

DESIGNED BY	AKC
DRAWN BY	SPK/CSB
CHECKED BY	AKC
DATE	JANUARY 20, 2011
SCALE	1"=600'

FIGURE 1

Approximate maximum extent of flood waters based on visible waterlines and damage





Slough that
received debris,
propane tanks and
drums

Photo #1



Photo #2



Photo #3



Fuel on the water in slough



Photo #4

Propane bottles, primarily 100 pound in the slough behind Middle Village.
Photo taken while standing on the road.



Photo #5

Propane bottles, drums and other debris

Photo #6

Looking down river towards rest of Middle Village, Lower Village is in the distance in the band of spruce.

Lower Village



Photo #7



Upper Village

Looking up river from Middle Village towards Upper Village

Photo #8

Aerial of Shop in Lower Village



Photo #9

Lower Village looking towards shop



On the road up to Lower Village hillside

Photo #10



Looking up river toward Middle Village from Lower Village on the hillside

Photo #11

