STATE OF ALASKA
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF FORESTRY

OP. NO: SE-88-016
OP. NAME: Dora Lake

NOTICE OF VIOLATION -COMPLAINT
AS41.17.133(a)

The undersigned State Forest Officer certified and says - That on the 23rd day of May, 1989 at 9:00 o'clock A M Location: SW1/4, NW1/4, Sec 25, T7S, R88E CRM - on 1100 Rd past Sta 110+00
Name: Reid Brothers Logging + Kootznoowoo Inc.
Last First (or Corporation) Middle Initial
City: See attached State: _____ ZIP: _____ Phone: See attached

Did then and there unlawfully commit the following offense:

☐ Failure to notify the Commissioner:
- ☐ Before operating on forest land (AS41.17.090)(c)
- ☐ Of proposed substantial change (AS41.17.090(g)
- ☐ Illegal commencement of operation (AS41.17.190)(f)

☒ Violation of regulation pertaining to:
- ☐ Harvesting (11AAC95.120)
- ☐ Reforestation (11AAC95.170)
- ☐ Log Transfer & Storage (11AAC95.150)
- ☐ Slash (11AAC95.110)
- ☒ Road Construction & Maintenance (11AAC95.110)
- ☐ Cleanup & Stabilization (11AAC95.130)
- ☐ Aesthetics (11AAC95.140)
- ☐ Insect & Disease Prevention and Control (11AAC95.180)
- ☐ Conversion of Forest Land to other Uses (AS41.17.110)

Note: A person who commits a violation is liable for a civil fine not to exceed $10,000.

Description of Violation: Blasting during road construction caused rock and debris to enter cataloged fish Habitat in violation of 11AAC 95.110(h)(1)

Damage or unsatisfactory condition resulting: Slide's exposed face, leads directly into cataloged habitat, and is a potential source of debris and sediment & 11AAC 95.110(g) 11AAC 95.130(d)
— See Attached Sheets for Details —

☒ Appearance not required. A hearing may be held at the request of the respondant.

The above named respondent shall appear before _____ (Hearing Officer)
Located at _____ at _____ M on the _____ day
of _____, 19_____ to answer the above charges.

The respondent shall be granted 10-day extensions up to a total of 60 days upon request. Hearing Officer, location and date to be announced.

5/24/89
Date

Christopher Westwood
Commissioner - ADNR
or Authorized Representative

Copies: Original-State, Yellow-Operator, Pink-Land Owner, Goldenrod-Timber Owner.

10-1036 (1/86)

10-1035
9/83

SE-88-016
Operation No.
Dora Lake
Name

STATE OF ALASKA
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF FORESTRY

FOREST PRACTICES INSPECTION REPORT

Operator: Reid Bros. Logging Date: May 23, 1989
Location: Dora Bay (Dora Lake) Type of Insepction OPERATIONAL
Travel Time: 4½ hours Priority V. High Inspection Time 5½ hrs.

Individual Present

Name	Representing	Name	Representing
Jim Reid	Reid Bros.		

This report pertains to recommendation(s) and/or regulation(s) pertaining to the following:

Reforestation ☐	Aesthetics ☐	Slash ☐
Road Construction & Maintenance ☐	Log Transfer & Storage ☐	Harvesting ☐
Wildlife Consideration ☐	Cleanup & Stabilization ☐	Other ☐

Recommendations/Required Action: The inspecting forester recommends the following actions in order to prevent violation of the Forest Practice Act.

—An N.O.V. is going to be issued—

2nd Slide on 1100 Rd - This section of road Traverses an area of shear cliffs that leads down into Dora Lake (Cataloged fish habitat). I was told that as construction was proceeding 8-10 shots had to be taken to construct the full bench Roadacross these cliffs. Jim told me that he purposely left the standing timber on the lower side of the road R/W to try and catch any rock or debris

This report indicates the conditions found to exist at the time of this inspection for those items checked or noted above. It does not imply that all parts of the operation were inspected nor does it indicate items not inspected are approved.

Signed: _____ Christopher Westwood
(Operator) State Forester or Authorized Representative

_____ 5/24/89
(Date) (Date)

Copies: Original-State, Yellow-Operator, Pink-Landowner, Goldenrod-Timber Owner.

SE-88-016
Dora Lake
5/23/89

That came down ~~the~~ during construction. Apparently as one of the last shots went off a large amount of material, mostly Rock and associated fines, broke loose and slid down the cliff and into the lake. Taking the trees and any other ~~debris~~ vegetative debris with it. The large block of material came from above the Road and, from what I was told, was not the road bench ~~itself~~ itself. I was told the lake did not turn cloudy just the area around the slide itself did and that the outlet water color, also did not change. (All were clear at the time of inspection) Jim said the Grapple Yarder was going to be moved in, in 3 or 4 days, and the floating chunks will be removed. They intend to leave any trees with attached root wads. This plan is acceptable and should be accomplished with no further ~~the~~ disturbance to the slide site. It is also ~~recco~~ recommended that some erosion control measures be ~~tak~~ taken, such as grass seeding ~~and~~ with an erosion control mat or fabric. (GeoJute, Curlex...etc). (I was told the slide took place 3 or 4 days ago) The largest component of this slide was rock and associated fines. The slope that remains below the road is 80-85%, and leads directly into the lake. ~~The~~ (150' wide x 250' long) If The road bank ravels; DO NOT Side Cast any Material along this stretch of road. Walked around the edge of Dora Lake and ribboned 12 Streams that are spawning and rearing habitat for anadromous fish species.

(AW)

SE-88-016
Dora Lake
5/23/89

3 of these were of significant size. 2 were located on the west side of Dora Lake and the 3rd on the eastern side ~~of~~ the end of the lake. These were ribboned, with blue + white fish flagging, to apoint about 600' up stream from the lake. All these streams are important and should be protected during falling and yarding and road construction operations. Even though roads cross far above habitat limits, minimize sediment introduced into these creeks, keep ditches open and functional and place culverts as work progresses. Directionally fall timber away from streams, do not buck any tree that enters ~~the~~ a stream, ~~bunk~~ & until it is removed at least one tree lenghth away. Keep debris out of creeks. Split line on Creeks and remove any debris that is deposited by logging. I was told that most of these creeks will not be logged ~~next~~ adjacent to because of lack of merchantable timber. Also many of the areas are ~~on~~ within the leave fringe ~~but~~ which will help greatly.

The area that is currently being logged, adjacent to Dora Lake, has a variable width (about 50') leave strip of trees and other undisturbed vegetation. This is excellent. The cutters have done a good job of directionally falling the timber and holding it on the steep hillside. The leave strip has protected the lake shore and several rivulets in the area. Yarding looks clean with a minimum of ground lead. This effort is appreciated.

Be careful with debris buildup and landing clean up on these landings that are located on steep slopes above surface waters. Clean debris to stable location and do not allow large accumulations to build upon the steep slopes.

CW

SE-88-016
Dora Lake
5/23/89

Rock Pit just Past 2nd Slide on 1100 road. Be sure ~~clearing~~ drainage from the pit goes away from the slide area. Deposit overburden in a stable location where it cannot enter surface waters. Load shots as light as possible. ~~Avoid~~

Large amount of important ~~fish~~ habitat around Miller Lake. I was told there is also alot of tough road building above this habitat. Please allow ample time for inspection and review by both DOF+ ADF&G, when this area is ~~is~~ notified for operation.

Christine Westwood
5/24/89

STATE OF ALASKA

DEPARTMENT OF NATURAL RESOURCES

DIVISION OF FORESTRY

STEVE COWPER, GOVERNOR

P.O. BOX 3361
KETCHIKAN, ALASKA 99901
PHONE (907) 225-3070

May 30, 1989

RECEIVED
JUN 02 1989
ALASKA DIV. OF FORESTRY

Jim Reid
Reid Timber, Inc.
2415 Hemlock, #104
Ketchikan, AK 99901

RE: Dora Lake (SE-88-016)

Dear Jim:

Enclosed is a Forest Practices Inspection Report and Notice of Violation (NOV) dated May 23, 1989. The report covers recommended forest practices to be used on Kootznoowoo, Inc.'s operations at Dora Lake. The NOV is for the second slide, into catalogued fish habitat, located along the 1100 road.

Please sign and return the original white copies of the inspection report to me.

Feel free to contact me concerning this report, the NOV, or forest practices in general.

Sincerely,

Bill Hanson
Ketchikan Forester

Enclosures: 2

cc/enc: J. Gustafson, ADF&G, Ketchikan
A. Kruse, ADEC, Juneau
D. Inglis, Log'N Road, Ketchikan
P. Joensuu, Kootznoowoo, Inc., Seattle
J. McAllister, DOF, Juneau

10-J32LH

STATE OF ALASKA

DEPARTMENT OF FISH AND GAME

HABITAT DIVISION

STEVE COWPER, GOVERNOR

2030 SEA LEVEL DRIVE
SUITE 205
KETCHIKAN, ALASKA 99901-6064
PHONE: (907) 225-2027

NOTICE OF VIOLATION

The undersigned says that prior to the 23 day of May, 19 89, Reid Brothers Logging and Construction, 2415 Hemlock #104, Ketchikan, Alaska 99901

did unlawfully violate the following Alaska State Statute AS 16.05.870

Describe: Blasting during road construction caused slides (rock and debris) to enter the cataloged fish habitat of Dora Lake (#102-40-10330-0010). Slide's exposed face is continued potential source of sedimentation.

The undersigned further states that this notice of violation is based upon his personal observations that the person named herein committed the offense contrary to law. The person named herein is to take the following steps by the ____ day of _____, 19____, to correct the violation cited above:

Take appropriate precautions to prevent similar occurrences in the future.

_____.

Jack Gustafson
(Signature, Fish and Game Official)

Area Habitat Biologist
(Title)

( ) Personally Served (X) Sent by mail by Jack Gustafson

on the 13 day of July, 19 89.

11-K69LH

STATE OF ALASKA

DEPARTMENT OF NATURAL RESOURCES

DIVISION OF FORESTRY

STEVE COWPER, GOVERNOR

P.O. BOX 3361
KETCHIKAN, ALASKA 99901
PHONE (907) 225-3070

May 30, 1989

Received

JUN 1 '89

Habitat Division
Ketchikan

Jim Reid
Reid Timber, Inc.
2415 Hemlock, #104
Ketchikan, AK 99901

RE: Dora Lake (SE-88-016)

Dear Jim:

Enclosed is a Forest Practices Inspection Report and Notice of Violation (NOV) dated May 23, 1989. The report covers recommended forest practices to be used on Kootznoowoo, Inc.'s operations at Dora Lake. The NOV is for the second slide, into catalogued fish habitat, located along the 1100 road.

Please sign and return the original white copies of the inspection report to me.

Feel free to contact me concerning this report, the NOV, or forest practices in general.

Sincerely,

Bill Hanson
Ketchikan Forester

Enclosures: 2

cc/enc: J. Gustafson, ADF&G, Ketchikan
A. Kruse, ADEC, Juneau
D. Inglis, Log'N Road, Ketchikan
P. Joensuu, Kootznoowoo, Inc., Seattle
J. McAllister, DOF, Juneau

10-J32LH

STATE OF ALASKA
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF FORESTRY

OP. NO: 52 10 016
OP. NAME: Nora Lake

NOTICE OF VIOLATION -COMPLAINT
AS41.17.133(a)

The undersigned State Forest Officer certified and says - That on the 23rd day of May, 1989 at 9:00 o'clock A M Location: SW¼, NW¼, Sec 25, T7S, R8E CRM - on 1100 Rd past Sta. 110+00
Name: Reid Brother's Logging + Kootznoowoo Inc.
Last First (or Corporation) Middle Initial
City: See attached State: _____ ZIP: _____ Phone: See attached

Did then and there unlawfully commit the following offense:

☐ Failure to notify the Commissioner:

☐ Before operating on forest land (AS41.17.090)(c)

☐ Of proposed substantial change (AS41.17.090(g)

☐ Illegal commencement of operation (AS41.17.190)(f)

☒ Violation of regulation pertaining to:

☐ Harvesting (11AAC95.120)

☐ Reforestation (11AAC95.170)

☐ Log Transfer & Storage (11AAC95.150)

☐ Slash (11AAC95.110)

☒ Road Construction & Maintenance (11AAC95.110)

☐ Cleanup & Stabilization (11AAC95.130)

☐ Aesthetics (11AAC95.140)

☐ Insect & Disease Prevention and Control (11AAC95.180)

☐ Conversion of Forest Land to other Uses (AS41.17.110)

Note: A person who commits a violation is liable for a civil fine not to exceed $10,000.

Description of Violation: Blasting during road construction caused rock and debris to enter cataloged fish Habitat in violation of 11AAC 95.110(b)(1)

Damage or unsatisfactory condition resulting: Slide's exposed face, leads directly into cataloged habitat, and is a potential source of debris and sediment & 11AAC 95.110(g) 11AAC 95.130(d)
— See Attached Sheets for Details —

☒ Appearance not required. A hearing may be held at the request of the respondant.

The above named respondent shall appear before _____ (Hearing Officer)
Located at _____ at _____ M on the _____ day
of _____, 19_____ to answer the above charges.

The respondent shall be granted 10-day extensions up to a total of 60 days upon request. Hearing Officer, location and date to be announced.

5/24/89
Date

Christopher Westwood
Commissioner - ADNR
or Authorized Representative

Copies: Original-State, Yellow-Operator, Pink-Land Owner, Goldenrod-Timber Owner.

10-1036 (1/86)

10-1035
9/83

SE-88-016
Operation No.
Dora Lake
Name

Page 1 of 4

STATE OF ALASKA
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF FORESTRY

FOREST PRACTICES INSPECTION REPORT

Operator: Ried Bros. Logging Date: May 23, 1989
Location: Dora Bay (Dora Lake) Type of Insepction OPERATIONAL
Travel Time: 4½ hours Priority V. High Inspection Time 5½ hrs.

Individual Present

Name	Representing	Name	Representing
Jim Reid	Reid Bros.		

This report pertains to recommendation(s) and/or regulation(s) pertaining to the following:

Reforestation ☐	Aesthetics ☐	Slash ☐
Road Construction & Maintenance ☐	Log Transfer & Storage ☐	Harvesting ☐
Wildlife Consideration ☐	Cleanup & Stabilization ☐	Other ☐

Recommendations/Required Action: The inspecting forester recommends the following actions in order to prevent violation of the Forest Practice Act.

—An N.O.V. is Going to be issued—

2nd Slide on 1100 Rd- This section of road Traverses an area of shear cliffs that leads down into Dora Lake (Cataloged fish habitat). I was told that as construction was proceeding 8-10 shots had to be taken to construct the full bench Roadacross these cliffs. Jim told me that he purposely left the standing timber on the lower side of the road R/W to try and catch any rock or debris

This report indicates the conditions found to exist at the time of this inspection for those items checked or noted above. It does not imply that all parts of the operation were inspected nor does it indicate items not inspected are approved.

Signed: _____ Christopher Westwood
(Operator) State Forester or Authorized Representative

_____ 5/24/89
(Date) (Date)

Copies: Original-State, Yellow-Operator, Pink-Landowner, Goldenrod-Timber Owner.

SE-88-016
Dora Lake
5/23/89

That came down ~~the~~ during construction. Apparently as one of the last shots went off a large amount of material, mostly Rock and associated fines, broke loose and slid down the cliff and into the lake. Taking the trees and any other ~~debris~~ vegetative debris with it. The large block of material came from above the Road and, from what I was told, was not the road bench ~~itself~~ itself. I was told the lake did not turn cloudy just the area around the slide itself did and that the outlet water color, also did not change. (All were clear at the time of inspection) Jim said the Grapple Yarder was going to be moved in, in 3 or 4 days, and the floating chunks will be removed. They intend ~~o~~ to leave any trees with attached root wads. This plan is acceptable and should be accomplished with no further ~~disturbance~~ disturbance to the slide site. It is also ~~recommended~~ recommended that some erosion control measures be ~~taken~~ taken, such as grass ~~seeding~~ seeding ~~and~~ with ~~an~~ an erosion control mat or fabric. (GeoJute, Curlex ...etc). (I was told the slide took place 3 or 4 days ago) The largest component of this slide was rock and associated fines. The slope that ~~is~~ remains below the road is 80-85%, and leads directly into the lake. ~~[redacted]~~ (150' wide x 250' long) If The road bank ravels; DO NOT Side Cast any Material along this stretch of road.

Walked around the edge of Dora Lake and ribboned 12 streams that are spawning and rearing habitat for anadromous fish species.

SE-88-016
Dora Lake
5/23/89

3 of these were of significant size. 2 were located on the west side of Dora Lake and the 3rd on the eastern side ~~of~~ the end of the lake. These were ribboned, with blue + white fish flagging, to apoint about 600' up stream from the lake. All these streams are important and should be protected during falling and yarding and road construction operations, Even though roads cross far above habitat limits; minimize sediment introduced into these creeks, keep ditches open and functional and place culverts as work progresses. Directionally fall timber away from streams, do not buck any tree that enters ~~the~~ a stream, ~~but~~ & until it is removed at least one tree length away. Keep debris out of creeks. Split line on creeks and remove any debris that is deposited by logging. I was told that most of these creeks will not be logged ~~next~~ adjacent to because of lack of merchantable timber. Also many of the areas are ~~on~~ within the leave fringe ~~but~~ which will help greatly.

The area that is currently being logged, adjacent to Dora Lake, has a variable width (about 50') leave strip of trees and other undisturbed vegetation. This is excellent. The cutters have done a good job of directionally falling the timber and holding it on the steep hillside. The leave strip has protected the lake shore and several rivulets in the area. Yarding looks clean with a minimum of ground lead. This effort is appreciated.

Be careful with debris buildup and landing clean up on these landings that are located on steep slopes above surface waters. Clean debris to stable location and do not allow large accumulations to build upon the steep slopes.

(CW)

SE-88-016
Dora Lake
5/23/89

Rock Pit just Past 2nd Slide on 1100 road. Be sure ~~drainage~~ drainage from the pit goes away from the slide area. Deposit overburden in a stable location where it cannot enter Suface waters. Load shots as light as possible. ~~end tok~~

Large amount of important ~~fish~~ habitat around Miller Lake. I was told there is also a lot of tough road building above this habitat. Please allow ample time for inspection and review by both DOF + ADF+G, when this area is ~~to be~~ notified for operation.

Christy Westwood
5/24/89