Photographs of the Chefornak Water Treatment Plant Lot – Lot 7, Block 2, Tract A, USS 4421
Photos with damaged railing were taken in June 2015. Photos with new railing were taken in July 2015.
The project will remove railing at the water treatment plant lot as requested by the contractor.

Picture #1-Existing Pump house 1. (Looking south)

Picture #2 Existing Pump House 1. (Looking South)

Photographs of the Chefornak Water Treatment Plant Lot – Lot 7, Block 2, Tract A, USS 4421
Photos with damaged railing were taken in June 2015. Photos with new railing were taken in July 2015.
The project will remove railing at the water treatment plant lot as requested by the contractor.

Picture #3-Existing Junction Box. (Looking East)

Picture #4-Existing Boardwalk. (Looking East)

Photographs of the Chefornak Water Treatment Plant Lot – Lot 7, Block 2, Tract A, USS 4421
Photos with damaged railing were taken in June 2015. Photos with new railing were taken in July 2015.
The project will remove railing at the water treatment plant lot as requested by the contractor.

Picture #5-Existing Well and boardwalk. (Looking east)

Picture #6-Existing well and Pump House 1. (Looking West)

Photographs of the Chefornak Water Treatment Plant Lot – Lot 7, Block 2, Tract A, USS 4421
Photos with damaged railing were taken in June 2015. Photos with new railing were taken in July 2015.
The project will remove railing at the water treatment plant lot as requested by the contractor.

Picture #7 –Existing Pump House 1. (Looking East)

Picture #8 – Existing well and Pump House 1. (Looking South)

Photographs of the Chefornak Water Treatment Plant Lot – Lot 7, Block 2, Tract A, USS 4421
Photos with damaged railing were taken in June 2015. Photos with new railing were taken in July 2015.
The project will remove railing at the water treatment plant lot as requested by the contractor.

Picture #9 – Existing pump house 1. (Looking Southwest)

Picture #10 – Power lines and boardwalk. (Looking West)

Photographs of the Chefornak Water Treatment Plant Lot – Lot 7, Block 2, Tract A, USS 4421
Photos with damaged railing were taken in June 2015. Photos with new railing were taken in July 2015.
The project will remove railing at the water treatment plant lot as requested by the contractor.

Picture #11 – existing well and boardwalk. (Looking west)

Picture #12 – Side rails. (Looking East)

Photographs of the Chefornak Water Treatment Plant Lot – Lot 7, Block 2, Tract A, USS 4421
Photos with damaged railing were taken in June 2015. Photos with new railing were taken in July 2015.
The project will remove railing at the water treatment plant lot as requested by the contractor.

Picture #13 – Side rails. (Looking southeast)

Picture #14 – Existing well connection to existing pump house 1. (Looking East)

Photographs of the Chefornak Water Treatment Plant Lot – Lot 7, Block 2, Tract A, USS 4421
Photos with damaged railing were taken in June 2015. Photos with new railing were taken in July 2015.
The project will remove railing at the water treatment plant lot as requested by the contractor.

Picture #15 – Existing well connection to existing pump house 1. (Looking East)

Picture #16 – Existing well connection to existing pump house 1. (Looking East)

Photographs of the Chefornak Water Treatment Plant Lot – Lot 7, Block 2, Tract A, USS 4421
Photos with damaged railing were taken in June 2015. Photos with new railing were taken in July 2015.
The project will remove railing at the water treatment plant lot as requested by the contractor.

Picture #17 – Existing Junction box. (Looking West)