Kuparuk River State #1 Exploratory Well Site

Permit Numbers:



to Rehabilitation Plan Completed activities Planned activities No planned activities (T)LVC: (Total) Live Vascular Cover



Photograph of Kuparuk River State #1 pad and airstrip taken in September 2001

	Performance Standards	Most Recent Recorded Progress Towards Performance Standards
<u>Gravel Pad and</u> <u>Airstrip</u>	Year 1: Site visually integrated with adjacent habitat Year 10: Site remains integrated with adjacent habitat	Due to the observed changes in the aerial photographs from 2003 to 2006, it is expected that this site will meet this standard.

					Work Completed					
*	Year		Planned Activities	Area	Site Element	Activity	Seed	Fertilizer	Data Summary	Reporting (Type and date of report)
A NAME OF A DESCRIPTION	Year O	2002	 Gravel removal and site preparation Inspect and photograph site 		<u>Gravel Pad and</u> <u>Airstrip</u>	 Gravel removed (~tundra grade or below) Inspected and photographed site 				 Rehabilitation Plan, February 2002 Site Closure Report, June 2002 Progress Report, 15 December 2002
_	Year 1	2003	 Inspect and photograph site 		<u>Gravel Pad and</u> Airstrip	 Inspected and photographed site Sampled soils for nutrient analysis 				– Progress Report, December 2003
	Year 3	2005	 Inspect and photograph site 	a n acres	Gravel Pad and Airstrip	Inspected and photographed site				– Progress Report, 13 December 2005
	Year 4	2006	 Inspect and photograph site 		Gravel Pad and Airstrip					
	Year 7	2009	 Inspect and photograph site 							– Final Report
	Year 10	2012	 Inspect and photograph site 							– Final Report

