

June 2020

From Evonne Reese's walk near Sandy Beach out to the end of the trail where the lower tailing pile is located.

These photos were taken after the maintenance addition of gravel to bring the overall cap thickness to 15 inches.

Lower tailings above the beach





From lower tailings down to the beach





Upper tailings (vegetation has grown in and it was hard to identify)





