Date:	5/20/23			
Time:	0832			
Recorder:	Officer McCollough			
Weather:	Sunny			
Wind Direction:	NNE Wind Speed (mph):	6.6 MPH	Temperature (°F)	48 °F

Description of Sheen: Not visible.

Not Visible	-	<b>Barely Visible</b>	-	Obvious	-	Obvious and requires additional action

Additional notes: No sheen, No odor, and No problems.

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date:	5/21/2023			
Time:	1610			
Recorder:	Officer McCollough			
Weather:	Sunny			
Wind Direction:	SSW Wind Speed (mph):	6.7 MPH	Temperature (°F):	52 °F

Description of Sheen: Not visible

Not Visible - Barely Visible - Obvious - Obvious and requires additional action


Additional notes:

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

**Obvious and requires additional action:** Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 5-23-23	
Time: 1446	-
Recorder: B. CASON	-
Weather: CLOUD-4	
Wind Direction: NE Wind Speed (mph):	17 Temperature (°F): 52
Description of Sheen:	
Not Visible - Barely Visible - Obvious	- Obvious and requires additional action
Additional notes:	
	······································

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.

Ŧ



Date: 5-24-23	
Time: 10:37	-
Recorder: B. CASON	_
Weather: CLOUP	_
Wind Direction: N Wind Speed (mph):	14 Temperature (°F): 46
Description of Sheen: Not Visible - Barely Visible - Obvious Additional notes:	- Obvious and requires additional action

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.

÷



Date: 5-25-23
Time: 14:09
Recorder: B. CASON
Weather: RAIN
Wind Direction: N Wind Speed (mph): 14 Temperature (°F): 247
Description of Sheen: Not Visible - Barely Visible - Obvious - Obvious and requires additional action Additional notes:

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.

Ŧ



Date: 5/27/23 Time: 1310

Recorder: Ben McCollough

Weather: Overcast/Rain/Wind

Wind Direction: SW Wind Speed (mph): 17 Temperature (°F): 48 °F

Description of Sheen: Not visible. Not Visible - Barely Visible - Obvious - Obvious and requires additional action Additional notes: Not able to smell or see any sheen.

Not Visible: no sheen visible Barely Visible: sheen is difficult to find, is less than approximately 25 square feet Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain



Date:			
5/28/23			
Time:	1320		
Recorder:	Ben Godfrey		
Weather:	Overcast/Showers		
Wind Direction:	W Wind Speed (mph): 9	Temperature (°F): 50 °F	
Description Not visible.			
Not Visible -	Barely Visible - Obvious	- Obvious and requires additional action	
Additional r Not able to sm	notes: ell or see any sheen.		

Not Visible: no sheen visible Barely Visible: sheen is difficult to find, is less than approximately 25 square feet Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain





