Date: 5-30-23	
Time: 15:20	
Recorder: B.CASON	
Weather: CLOUD Y	_
Wind Direction: 5W Wind Speed (mph):	18 Temperature (°F): 45
Decrease 601	
Description of Sheen:	
Not Visible - Barely Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 5	-31-	23		
Time: 8):27			
Recorder:	B. CAS	on		
Weather:	SOUN			
Wind Direction:	S	Wind Speed (mph): 15	Temperature (°F):	45

Description of Sheen:

Not Visible	-	Barely Visible	-	Obvious	-	Obvious and requires additional action
Additiona	ıl n	otes:				
			<u></u>			-

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: (e-1-23	
Time: 2	IH PM	
Recorder: B). CASON	
Weather: 01	L0704	
Wind Direction:	S Wind Speed (mph):	8. Temperature (°F): 48
	·	
Description of	Sheen:	
Not Visible -	Barely Visible - Obvious	- Obvious and requires additional action
Additional no	ites:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 6-2-23 Time: 11:48	
Time: 11:48	
Recorder: B. CASON	
Weather: CLOUDY/WINDY	
	2 Temperature (°F): 47
Description of Sheen:	
Not Visible - Barely Visible - Obvious -	Obvious and requires additional action
Additional notes:	
e'	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



DailyCheck—Kenai Beach Sheen

Date: 6-3-23				
Time: 1030				
Recorder:Marinko	ovski			
Weather: Cloudy				
Wind Direction: WNW	Wind Sp	eed (mph): 8	Temperature (°F):	47
Description of Sh	een: Not visib	ole Obvious -	Obvious and requires	additional action
Additional notes	5:			

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken

File: 0600-004-033



DailyCheck—Kenai Beach Sheen

Date: 6-4-2023	_
Time: 1557	_
Recorder:Wesley Howard Clark	_
Weather: Cloudy	_
Wind Direction: Variable Wind Speed (mph): <	5knts Temperature (°F): 46
Description of Sheen: NONE Not Visible - Barely Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken

File: 0600-004-033



ction
3

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 6/6/23	2
Time: //30	
Recorder: M. La Viguew	
Recorder: M. La Viguew Weather: Cloudy	
Wind Direction: Wind Speed (mph):	Temperature (°F):
ENE 13mph	59
Description of Sheen: Not Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 6/8/23		
Time: 1:00 7	°W	
Recorder: 9.7	ATE	
Weather: (0)°	OVERCAST/SU	GHT RAIN
Wind Direction:	Wind Speed (mph):	Temperature (°F):
SW	9	60
Not Visible - Barely Additional notes:	en: NO SHEEK Visible - Obvious -	Obvious and requires additional action

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date:		_
Time:		_
Recorder:		_
Weather:		_
Wind Directio	n: Wind Speed (mph):	Temperature (°F):
Description	n of Sheen:	
Not Visible	- Barely Visible - Obvious	- Obvious and requires additional action
Additiona	I notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date:	6-10-23					
Time:	0759					
Recorder:	M. Mod	rell				
Weather:	Cloudy					
Wind Direction:	N	Wind Spe	ed (mph):	4	Temperature (°F):	46
Description (of Sheen:	Not Visible	e			
Not Visible -	Barely Vi	sible -	Obvious	-	Obvious and requires	additional action
Additional r	notes:					

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



DailyCheck—Kenai Beach Sheen

Date: 6/11/23			
Time:1339			
Recorder:Ben Godfrey			
Weather: Cloudy			
Wind Direction: West	Wind Speed (mph): 12	Temperature (°F):	53
Description of Sheen:	NONE		
Not Visible - Barely Vis	ible - Obvious -	Obvious and requires	additional action
Additional notes:			
No sight or smell of any sheen.			

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken

File: 0600-004-033

