1 1	•
Date: 6 26 23	_
Time: (2:15	
Recorder: B. CASON	_
Weather: CLOUDY	
Wind Direction: Wind Speed (mph):	3 Temperature (°F): 50
•	
Description of Sheen:	
Not Visible - Barely Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.

File: 0400-033-004



. / /
Date: 6/27/23
Time: 8:22
Recorder: R. Cason
Weather: RAIN
Wind Direction: Wind Speed (mph): 5 Temperature (°F): 4
Description of Sheen:
lot Visible - Barely Visible - Obvious - Obvious and requires additional action
Additional notes:

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented



Date: 6/28/23	•
Time: 3:28 PM	
Recorder: B, Cason	_
Weather: CLOUD Y	_
Wind Direction: Wind Speed (mph):	© Temperature (°F): 56
	,–
Description of Sheen:	
Not Visible - Obvious	- Obvious and nameiras state as a last to
Additional notes:	- Obvious and requires additional action

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.

File: 0400-033-004



Date: 7-1-23				
Time: 1440				
Recorder: Colton He	rrick			
Weather: Sunny				
Wind Direction: 0	Wind Speed (mph): 0	Temperature (°F):	55
Description of Shee	en: NONE			
Not Visible - Barely	Visible - Obviou	ıs -	Obvious and requires	additional action
Additional notes:				

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken



Date: 7-2-2023				
Time: 1559				
Recorder:Jere	my Godfrey			
Weather: Clou	dy/Rainy			
Wind Direction: N	Winc	Speed (mph): 7.5	Temperature (°F):	54.9
Description of	Sheen: NON	E		
Not Visible -	Barely Visible	- Obvious -	Obvious and requires	additional action
Additional no	tes:	•		

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken



Date: 7523		·
Time: 121210	_	
Recorder: B. CASON	_	
Weather: CLOUDY	_	
Wind Direction: Wind Speed (mph):	Temperature (°F):	51
	`	·
Description of Sheen:		
Not Visible - Obvious	- Obvious and requires a	idditional action
Additional notes:		

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.

File: 0400-033-004

ENV-KR064 Kenai Beach Sheen Daily Checklist



11/23	·
Date: 0 0	_
Time: 15:37	
Recorder: B. CASON	
Weather: RAID	_
Wind Direction: Wind Speed (mph):	Temperature (°F): 54
	, ,
Description of Sheen:	
Not Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.

File: 0400-033-004



Date: 7-8-23			
Time: 1353			
Recorder:K. Butler			
Weather: Cloudy			
Wind Direction: SW	Wind Speed (mph): 10	Temperature (°F):	53
Description of Shoon:			
Description of Sheen:			
Not Visible - Barely Vis	ible - Obvious -	Obvious and requires	additional action
Additional notes:			

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken



Date: 7/9/23			
Time:1330			
Recorder:Ben Godfrey			
Weather: Clear			
Wind Direction: NE	Wind Speed (mph): 8	Temperature (°F):	53
Description of Sheen:	Not visible nor detect	able by smell.	
Not Visible - Barely Vis	sible - Obvious	- Obvious and requires	additional action
Additional notes:	•	•	
None			

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken

