Date:	10/16/23		
Time:	8:63		
Recorder:	B. CASON		
Weather:	CLOUDY	_	4
Wind Direction:	Wind Speed (mph):	72/3 Temperature (°F):	46°
		102	
Description (of Sheen:		
Not Visible -	Barely Visible - Obvious	- Obvious and requires a	additional action
Additional n	notes:		

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date:	10/17/23	_	
Time:	10:09	_	
Recorder:	B. Cason	_	
Weather:	CLOUDY	_	3
Wind Direction:	Wind Speed (mph):	Z_Temperature (°F):	38°
Description of	of Sheen:		
Not Visible -	Barely Visible - Obvious	- Obvious and requires	additional action
Additional n	otes:		

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 10/18/23	
Time: //- 4/	
Recorder: B. CASON	
Weather: SUNNY	_
Weather: SUNN Y Wind Direction: We Wind Speed (mph):	5 Temperature (°F): 40
Description of Sheen:	
Not Visible - Barely Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Additional						
Additional r	notes:					
Not Visible -	Barely Vi	sible -	Obvious	-	Obvious and require	es additional action
Description (of Sheen:					
Wind Direction:	NNE	Wind Speed	d (mph):	6	Temperature (°F):	39
<u>Weather:</u>	Clear					
Recorder:	MLehl					
Time:	14:00					
Date:	10/19/2	2023				

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

 $\textbf{Obvious:} \ \text{clearly visible upon approach, boom at the base of the bluff is appropriate to contain}$

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



A .	
Date: 10 23 23	
Time: 12:30	
Recorder: B. CASON	
Weather: CLOVDY	
Wind Direction: Wind Speed (mph):	// Temperature (°F): 37°
Description of Sheen:	
Not Visible - Barely Visible - Obvious	- Obvious and requires additional action
Additional notes:	
Additional flotes.	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 10/24/23	-
Time: 12:10	_
Recorder: B. CASON	_
Weather: SUNNY	_
Wind Direction: NE Wind Speed (mph):	9 Temperature (°F): 36°
•	1 -
Description of Sheen:	
Not Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date: 10-25-23	
Time: 12:00	
Recorder: B. CASON	_
Weather: วิบพม	_
Wind Direction: Wind Speed (mph):	3 Temperature (°F): 37
Description of Sheen:	
ot Visible - Barely Visible - Obvious	- Obvious and requires additional action
Additional notes:	

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



Date:	10-26-	23			
Time:	10:18				
Recorder:	B. Cason				
Weather:	FAIR		· .		
Wind Direction:	NE W	ind Speed (mph):	Ø	Temperature (°F):	27°
5	f of			,	
Description (of Sheen:				
Not Visible -	Barely Visible	- Obvious	- 0	bvious and requires	additional action
Additional n	otes:				

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken.



DailyCheck—Kenai Beach Sheen

Date: 10-27-23			
Time:noonish		_	
Recorder:whc		_	
Weather: mostly sunr	у		
Wind Direction: none	Wind Speed (mph):	Ten	nperature (°F):
Description of Sheer	1: not visible		
Not Visible - Barely V		- Obviou	is and requires additional action
Additional notes:			

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken

File: 0600-004-033



DailyCheck—Kenai Beach Sheen

Date: 10-28-23			
Time:noonish		_	
Recorder:wwc		_	
Weather: mostly sunn	у	_	
Wind Direction: none	Wind Speed (mph):	Temperature (°F):	34
Description of Sheer	not visible		
Not Visible - Barely V	isible - Obvious	- Obvious and requires	s additional action
Additional notes:			

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken

File: 0600-004-033



DailyCheck—Kenai Beach Sheen

Date: 10-29-23			
Time: noonish			
Recorder:whc			
Weather: mostly sunny	,		
Wind Direction: S	Wind Speed (mph): 15	Temperature (°F):	38
Description of Shoon			
Description of Sheen:	not visible		
Not Visible - Barely Vi	sible - Obvious -	Obvious and requires	additional action
Additional notes:			

Not Visible: no sheen visible

Barely Visible: sheen is difficult to find, is less than approximately 25 square feet

Obvious: clearly visible upon approach, boom at the base of the bluff is appropriate to contain

Obvious and requires additional action: Additional resources are required to contain the sheen, follow-up with documented actions taken

File: 0600-004-033

