

State of Alaska > DEC > EH > DW

DRINKING WATER PROGRAM

WELCOME




QUICK LINKS

- ▶ Drinking Water Protection
 - Participate in Groundwater Protection and Water Wells stakeholder
 - Map of Drinking Water Protection Areas
 - Sanitary Survey Program
 - PWS Emergency Preparedness
 - Engineering
 - Drinking Water Forms
 - Drinking Water Publications
 - ▶ Drinking Water Watch**
- ▶ Certified Micro Laboratories
- ▶ Certified Chem Laboratories
- ▶ Electronic Data Reporting System (For

Our mission is to protect public health by ensuring that all people have access to safe drinking water. We work with public

Navigate to the [Drinking Water Homepage](#) and under Quick Links select **Drinking Water Watch**

DRINKING WATER WATCH

SEARCH SYSTEMS AND SAMPLES

PUBLIC WATER SUPPLY SYSTEMS SEARCH PARAMETERS

Water System No.

Water System Name

Region Served: All

Water System Type: All

Primary Source Water Type: All

Point of Contact Type: None

Type in PWSID or Water System Name

Click **Search for Water Systems** button

DRINKING WATER WATCH

WATER SYSTEMS

Water System No.	Water System Name	Status	Region Served
AK2227563	PALMER CHURCH OF CHRIST	A	MATANUSKA-SUSITNA
AK2227424	PALMER CHURCH OF CHRIST	A	MATANUSKA-SUSITNA
AK2227582	PALMER ELKS LODGE	A	MATANUSKA-SUSITNA
AK2227432	PALMER FAMILY CHURCH	A	MATANUSKA-SUSITNA
AK2227482	PALMER GOLF COURSE CLUBHOUSE	A	MATANUSKA-SUSITNA
AK2227555	PALMER KINGDOM HALL	A	MATANUSKA-SUSITNA
AK2226039	PALMER SEVENTH DAY ADVENTIST CHURCH	A	MATANUSKA-SUSITNA
AK2226020	PALMER WATER SYSTEM	A	MATANUSKA-SUSITNA

Select your system by clicking on the **PWSID**

DRINKING WATER WATCH

WATER SYSTEM DETAILS

Water System No.: AK2226020

Water System Name: PALMER WATER SYSTEM

Federal Type: Community

Principal County Served: MATANUSKA-SUSITNA

Primary Source: GW

Help with this page

Water System Facilities	Source Water Assessment Results	Non-Coliform Samples/Results
Coliform/Microbial Sample Results	Source Water Assessment Web Map	Non-Coliform Samples/Results by Analyte
Coliform Sample Summary Results	Lead And Copper Sample Summary Results	Violations/Enforcement Actions
Sample Schedules	Site Visits	Milestones
Current Monitoring Summary		

Click on **Current Monitoring Summary**

Monitoring Summary for PALMER WATER SYSTEM

Public water system ID#AK2226020 Population: 8087

Community Water System, Ground water

March 30, 2016

Requirement	Required Sampling Frequency	Last Sample	Next Sample
Sanitary Survey	Every 3 years	02/25/2015	
DS001 DS PALMER WATER SYSTEM			
COLIFORM (TCR)	9 sample(s) monthly	03/03/2016	Monthly- according to your sample site plan (new RTCR

Check the date of the monitoring summary to make sure it's for the current year